



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Red
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-30
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	35
Total items failed	7

MOT #17 2022-07-19 09:09

MOT test number 231742892381

Result ✓ Passed

Next expiry date 2023-07-28

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16 2022-07-19 09:09

MOT test number 220250227712

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15** 2021-07-29 12:27**MOT test number** 947366590320**Result** ✓ Passed**MOT #14** 2021-01-22 13:17**MOT test number** 109838203291**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2020-01-28 12:01**MOT test number** 132729131508**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #12** 2020-01-27 14:25**MOT test number** 178077634838**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**DANGEROUS** Nearside Front Valve stem seriously damaged (5.2.3 (j))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))**DANGEROUS** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**DANGEROUS** Offside Front Valve stem seriously damaged (5.2.3 (j))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**MOT #11** 2018-12-31 14:26**MOT test number** 418923258060**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2018-12-19 17:27**MOT test number** 197173475657**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Rear Position lamp not working (4.2.1 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2018-01-03 10:38**MOT test number** 623406151604**Result** ✓ Passed**MOT #8** 2017-01-04 09:09**MOT test number** 139558425941**Result** ✓ Passed**MOT #7** 2016-01-20 10:16**MOT test number** 225440737538**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre has cut on inner sidewall and inner wearing worn.**Advice** Exhaust heat cover is loose**Advice** Offside Front Tyre inner edge wearing worn

**MOT #6** 2016-01-20 10:16**MOT test number** 437779638420**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre inner edge wearing worn**Advice** Nearside Rear Tyre has cut on inner sidewall and inner wearing worn.**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Exhaust heat cover is loose**MOT #5** 2015-01-29 12:57**MOT test number** 138219825078**Result** ✓ Passed**MOT #4** 2014-02-26 09:20**MOT test number** 437647154014**Result** ✓ Passed**MOT #3** 2014-02-24 16:42**MOT test number** 636645454074**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-02-26 12:10**MOT test number** 856497153062**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-02-18 12:54
MOT test number	577719143035
Result	✗ Failed
Fail	Offside Headlamp aim too low (1.8)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
30 September 2022

✕
MOT

Expired:
28 July 2023

Tax status	Expired at 30 September
Days left	576 days too late
MOT expiry date	28 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WJ10USG
Plate since	2019-09-28
Current registration	WJ10USG
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2022-07-19
Complete history	See info



Registration #1	2010-03-01	16 mi
Registration #2	2013-02-18	69.721 mi
Registration #3	2013-02-26	70.001 mi
Registration #4	2014-02-24	80.878 mi
Registration #5	2014-02-26	80.881 mi
Registration #6	2015-01-29	87.637 mi
Registration #7	2016-01-20	97.410 mi
Registration #8	2016-01-20	97.410 mi
Registration #9	2017-01-04	105.984 mi
Registration #10	2018-01-03	115.420 mi
Registration #11	2019-01-03	125.000 mi
Registration #12	2019-01-03	125.000 mi
Registration #13	2019-01-03	125.000 mi
Registration #14	2019-01-03	125.000 mi
Registration #15	2019-01-03	125.000 mi
Registration #16	2019-01-03	125.000 mi
Registration #17	2019-01-03	125.000 mi
Registration #18	2019-01-03	125.000 mi
Registration #19	2019-01-03	125.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602