





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	White
Year of manufacture	2015
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



## Internet history

E	n	t	r	y	1	

Lifety 1	
Date	2021-07-22
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



	~		
10/1/	<b>1</b>	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-07-21
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #8	2023-07-13 14:43
MOT test number	549764256284
Result	✓ Passed
Next expiry date	2024-07-21

MOT #7	2022-07-09 07:44
MOT test number	378271048657
Result	✓ Passed

MOT #6		2021-07-22 15:31
MOT test	number	309910399861
Result		✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (3	1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.3	1.14 (a) (ii))

MOT #5	2020-11-19 12:56
MOT test number	632040217223
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4 2019-09-26 09:35

**MOT test number** 469068068959

**Advice** Engine and under body covers

**Advice** Offside Outer sill cover

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Outer sill cover

MOT #3 2018-09-25 09:40

MOT test number 787800604967

Result \square Passed

**Advice** Engine and under body covers

**Advice** Offside Outer sill cover

**Advice** Nearside sill cover

MOT #2 2018-09-25 09:40

MOT test number 580697166796

**Result** X Failed

**Advice** Nearside sill cover

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

**Advice** Engine and under body covers

**Advice** Offside Outer sill cover

**MOT #1** 2017-09-27 13:43

**MOT test number** 559078742458

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-


CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET STATE OF THE STATE OF TH	
********	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-10
Last registration	2023-07-13
Complete history	See info



Registration #1	2015-01-10	17 mi
Registration #2	2017-09-27	40.520 mi
Registration #3	2018-09-25	49.680 mi
Registration #4	2018-09-25	49.680 mi
Registration #5	2019-09-26	58.102 mi
Registration #6	mm.m.m	11.777 46
	**************************************	11,777 es
Registration #6	900-0-0 900-0-0 900-0-0	11.777 ea 21.777 ea 21.777 ea
Registration #6 Registration #7	100-10-10 1000-10-10 1000-10-10	11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

**Engine number** D4FDEU476714