



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Grey
Year of manufacture	2006
Top speed	116 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.150 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-28
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-08
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	39
Total items failed	7

MOT #20	2023-06-23 15:26
MOT test number	166601827874
Result	✓ Passed
Next expiry date	2024-07-08
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19	2023-06-22 09:52
MOT test number	725273246965
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #18**

2022-07-06 09:15

**MOT test number**

817162518100

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**MOT #17**

2022-06-30 08:16

**MOT test number**

250770571110

**Result**

✗ Failed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect lens deteriorated and bulb fitted incorrectly (4.1.2 (c))
- Advice** Front Direction indicator slightly discoloured both sides (4.4.3 (a))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect lens deteriorated (4.1.2 (c))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

**MOT #16** 2021-07-09 16:18**MOT test number** 830429262624**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))**MOT #15** 2020-09-04 13:18**MOT test number** 779149030453**Result** ✓ Passed**MOT #14** 2020-09-04 13:18**MOT test number** 962554427345**Result** ✗ Failed**Pass with rectification** Horn not working (7.7 (a) (ii))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #13** 2019-08-16 07:58**MOT test number** 710666823735**Result** ✓ Passed**Advice** Headlight aims cloudy but still met the required standard**MOT #12** 2018-08-25 08:52**MOT test number** 320578192674**Result** ✓ Passed**Advice** Headlight lenses starting to go cloudy**Advice** Child seat fitted offside rear, unable to check adult seat belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

**MOT #11** 2017-08-31 10:08**MOT test number** 713676743413**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2017-08-26 08:30**MOT test number** 514030688452**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp aim beam image obviously incorrect no beam pattern (1.8.A.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Headlamp aim beam image obviously incorrect no beam pattern (1.8.A.1b)**MOT #9** 2016-08-27 09:14**MOT test number** 844884037116**Result** ✓ Passed**MOT #8** 2016-08-27 09:14**MOT test number** 572112005452**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #7** 2015-08-08 08:29**MOT test number** 513001500289**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-08-15 09:59**MOT test number** 815867024241**Result** ✓ Passed**MOT #5** 2013-08-08 08:50**MOT test number** 248990023278**Result** ✓ Passed**MOT #4** 2012-08-11 09:47**MOT test number** 367064822222**Result** ✓ Passed**MOT #3** 2011-08-12 09:07**MOT test number** 656844421220**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-08-10 09:32**MOT test number** 792702620256**Result** ✓ Passed



MOT #1	2009-08-17 17:16
MOT test number	123029429266
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
8 July 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	8 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-22
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2006-09-22	18 mi
Registration #2	2009-08-17	19.450 mi
Registration #3	2010-08-10	23.545 mi
Registration #4	2011-08-12	28.516 mi
Registration #5	2012-08-11	33.576 mi
Registration #6	2013-08-08	38.960 mi
Registration #7	2014-08-15	44.613 mi
Registration #8	2015-08-08	47.563 mi
Registration #9	2016-08-27	51.185 mi
Registration #10	2016-08-27	51.185 mi
Registration #11	2017-08-26	53.135 mi
Registration #12	2019-06-20	55.277 mi
Registration #13	2019-06-20	55.277 mi
Registration #14	2019-06-20	55.277 mi
Registration #15	2019-06-20	55.277 mi
Registration #16	2019-06-20	55.277 mi
Registration #17	2019-06-20	55.277 mi
Registration #18	2019-06-20	55.277 mi
Registration #19	2019-06-20	55.277 mi
Registration #20	2019-06-20	55.277 mi
Registration #21	2019-06-20	55.277 mi
Registration #22	2023-06-23	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1825 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	6S66240