





report date: 2024-03-28

General information

Make	FIAT
Model	500C S
Colour	Green
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-29

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

Μ	OT	his	tory

MOT expiry date	2025-04-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	8
Total items failed	9

MOT #10	2024-04-18 11:23
MOT test number	258464466126
Result	✓ Passed
Next expiry date	2025-04-20

MOT #	9 2024-04-17 10:23	
MOT te	est number 386742707240	
Result	▼ Failed	
Fail	Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Fail is 1.0n	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required nm (5.2.3 (e))	
Fail	Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Fail require	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth ed is 1.0mm (5.2.3 (e))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #8	2023-03-31 09:24
MOT test number	357502351483
Result	✓ Passed
MOT #7	2022-04-21 11:22
MOT test number	758153025918
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

Fail

EK64UOF

report date: 2024-03-28

× Failed

MOT #6

MOT test number

297544635847

Result

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #5

MOT test number

890340861568

Result

✓ Passed

MOT #4 2020-03-12 15:06

MOT test number 782557358615

Result X Failed

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

 MOT #3
 2019-03-09 12:39

 MOT test number
 288056022452

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-03-09 10:34

MOT test number 118162796962

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2018-03-12 15:56
MOT test	number	178787887890
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners Check it in the premium report and see all owner registrations. Download the full report	

THE STREET STREET, STR	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK SIE
Plate since	
Current registration	UK SIE
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-28
Last registration	2024-04-18
Complete history	See info



2014-11-28	11 mi
2018-03-12	42.348 mi
2019-03-09	49.143 mi
2019-03-09	49.143 mi
2020-03-12	55.888 mi
2020-03-12	55.888 mi
	11.777 es
	11.777 es
	91.777 esi
	11.777 es
	11.777 es
	2018-03-12 2019-03-09 2019-03-09 2020-03-12

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 0709926