





report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Blue
Year of manufacture	2012
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-05-22

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-04-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #9		2021-04-09 16:27
MOT test	number	153516139846
Result		✓ Passed
Next expi	ry date	2022-04-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #8	2021-04-08 16:11
MOT test number	292308219303
Result	X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Rear Registration plate lamp does not illuminate simultaneously wi	ith the position lamps
(4.7.2 (a))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #7 2020-03-10 10:18

MOT test number 869993412773

Result Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Rear Direction indicator slightly discoloured both (4.4.3 (a))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

MOT #6 2019-03-20 14:21

MOT test number 112557908321

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2019-03-16 09:38

MOT test number 615435037594

Result ★ Failed

Fail Offside Front Side repeater not working (4.4.1 (a) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2018-03-17 13:44

MOT test number 250959241489

Advice Nearside Front tyre tread low

CarCheck.co.uk page 4/12



MOT #3 2017-03-01 09:46

MOT test number 171437359293

Result ✓ Passed

Advice Nearside Rear tyre cracking in tread pattern

Advice Offside Rear tyre cracking in tread pattern

Advice Engine covers and under trays fitted obscuring some engine and chassis components

MOT #2 2016-03-21 11:46

MOT test number 269373779517

Result \(\sqrt{Passed} \)

Advice Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2015-03-02 10:54

MOT test number 419421065066

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax expired: 29 December 2021 MOT

Expired:
8 April 2022

Tax status Expired at 29 December 2021

Days left 853 days too late

MOT expiry date 8 April 2022

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when misterly		
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		/e?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-03-08
Last registration	2021-04-09
Complete history	See info



Registration #1	2012-03-08	22 mi
Registration #2	2015-03-02	64.259 mi
Registration #3	2016-03-21	71.225 mi
Registration #4	2017-03-01	81.351 mi
Registration #5	2018-03-17	92.518 mi
Registration #6	2019-03-16	106.604 mi
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		10.307 mg

More info >

CarCheck.co.uk page 11/12



VO12XNT

report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number CAYCR58709