



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	White
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-04
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-02
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #9 2024-01-30 09:44

MOT test number 656962083065

Result ✓ Passed

Next expiry date 2025-02-02

Advice Front Lower Suspension arm ball joint has slight play Both sides nearside worse (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))

MOT #8 2023-02-01 12:55

MOT test number 289304493826

Result ✓ Passed

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2023-01-30 13:00

MOT test number

160852310213

Result**✗ Failed****Fail**

Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6

2022-02-01 13:11

MOT test number

335667101130

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge & perrished (5.2.3 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

2022-02-01 13:11

MOT test number

701498265347

Result**✗ Failed****Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Pass with rectification

Front Position lamp not working Both sides (4.2.1 (a) (ii))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge & perrished (5.2.3 (e))

**MOT #4** 2021-01-28 10:23**MOT test number** 810501348356**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2020-02-03 12:00**MOT test number** 609716170700**Result** ✓ Passed**MOT #2** 2018-05-01 14:52**MOT test number** 172122274943**Result** ✓ Passed

Advice Front Tyre worn close to the legal limit Both sides (4.1.E.1)

Advice Rear seat belts not checked as seats folded down and goods and equipment stored in rear

MOT #1 2017-03-23 12:46**MOT test number** 244798650953**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-30
Last registration	2024-01-30
Complete history	See info



Registration #1	2014-03-30	12 mi
Registration #2	2017-03-23	50.741 mi
Registration #3	2018-05-01	59.954 mi
Registration #4	2020-02-03	79.046 mi
Registration #5	2021-01-28	86.165 mi
Registration #6	2022-01-28	95.277 mi
Registration #7	2022-01-28	95.277 mi
Registration #8	2022-01-28	95.277 mi
Registration #9	2022-01-28	95.277 mi
Registration #10	2022-01-28	95.277 mi
Registration #11	2022-01-28	95.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1073 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	G4LAEM230911
---------------	--------------