




report date: 2024-12-14

General information

Make	VAUXHALL
Model	CORSA ACTIVE CDTI
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-28
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-09-07
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	5
Total items failed	8

MOT #7	2024-08-24 09:47
MOT test number	753034609209
Result	✓ Passed
Next expiry date	2025-09-07

MOT #6	2024-08-22 09:55
MOT test number	853510755393
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases rear joint (6.1.2 (a))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5	2023-08-24 15:28
MOT test number	317372228780
Result	✓ Passed
Advice	Rear exhaust section corroded but not excessive



MOT #4	2023-08-22 12:05
MOT test number	510371855483
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Rear exhaust section corroded but not excessive
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #3	2022-08-20 13:08
MOT test number	701101655156
Result	✓ Passed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #2	2022-08-15 10:56
MOT test number	628458071087
Result	✗ Failed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #1	2021-09-08 13:32
MOT test number	335444710872
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 September 2025

✓
MOT

Expires:
7 September 2025

Tax status Valid until 1 September

Days left 225

MOT expiry date 7 September 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	Start	End
Owner 2	Start	End
Owner 3	Start	End
Owner 4	Start	End
Owner 5	Start	End
Owner 6	Start	End

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates: 1

Current registration: YKZ4768

Plate since: 2019-09-29

Current registration: YKZ4768

Plate since: 2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2010-01-05
Last registration	2024-08-24
Complete history	See info



Registration #1	2010-01-05	21 mi
Registration #2	2010-08-20	25.277 mi
Registration #3	2021-09-08	68.267 mi
Registration #4	2022-08-15	70.623 mi
Registration #5	2022-08-20	70.680 mi
Registration #6	2023-05-20	75.277 mi
Registration #7	2023-05-20	75.277 mi
Registration #8	2023-05-20	75.277 mi
Registration #9	2024-08-24	75.277 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★★
Video [see crash video](#)



Dimensions & weight

Width	1713 mm
Height	1488 mm
Length	3999 mm
Wheel base	2511 mm
Kerb weight	1150 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	3415224