



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Black
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	106 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.2 mpg



LABEL UNKNOWN



MOT history

MOT #15	2021-03-02 15:00
MOT test number	461520939498
Result	✓ Passed
Next expiry date	2022-03-01

MOT #14	2020-02-13 08:08
MOT test number	942695859898
Result	✓ Passed

MOT #13	2019-01-24 09:18
MOT test number	272991436089
Result	✓ Passed

MOT #12	2018-01-22 08:09
MOT test number	746693510221
Result	✓ Passed

MOT #11	2018-01-22 08:09
MOT test number	164024601307
Result	✗ Failed

Pass with rectification Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #10	2017-01-23 09:00
MOT test number	180814126353
Result	✓ Passed

MOT #9	2016-02-15 08:36
MOT test number	947651767341
Result	✓ Passed

Advice Nearside Rear tyre side wall deteriorated

**MOT #8** 2015-02-05 09:01**MOT test number** 709916735016**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-02-04 09:52**MOT test number** 535415434006**Result** ✓ Passed**MOT #6** 2014-02-03 08:54**MOT test number** 599054934019**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2013-02-22 10:22**MOT test number** 456393653068**Result** ✓ Passed**MOT #4** 2012-01-17 08:58**MOT test number** 805767812080**Result** ✓ Passed**MOT #3** 2011-01-19 08:44**MOT test number** 269769711055**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)



MOT #2	2011-01-19 08:44
MOT test number	426879711009
Result	✓ Passed

MOT #1	2010-01-18 16:55
MOT test number	503828410009
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-01-24
Last registration	2021-03-02
Complete history	See info



Registration #1	2007-01-24	20 mi
Registration #2	2010-01-18	21.741 mi
Registration #3	2011-01-19	28.671 mi
Registration #4	2012-01-17	30.200 mi
Registration #5	2013-02-22	39.807 mi
Registration #6	2014-02-03	44.768 mi
Registration #7	2014-02-04	44.768 mi
Registration #8	2015-02-05	50.177 mi
Registration #9	2015-03-02	55.377 mi
Registration #10	2015-03-02	55.377 mi
Registration #11	2015-03-02	55.377 mi
Registration #12	2015-03-02	55.377 mi
Registration #13	2015-03-02	55.377 mi
Registration #14	2015-03-02	55.377 mi
Registration #15	2015-03-02	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1565 mm
Length	4100 mm
Wheel base	2500 mm
Kerb weight	1145 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1249434