



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-15
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-18
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8	2024-04-15 14:42
MOT test number	756825262377
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #7	2023-04-17 10:12
MOT test number	489002466025
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2022-04-08 09:37
MOT test number	273089282526
Result	✓ Passed

**MOT #5** 2021-04-19 15:58**MOT test number** 421770169508**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Engine cover fitted and undertrays fitted
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2019-04-13 08:08**MOT test number** 491047008191**Result** ✓ Passed

- Advice** Offside indicator side repeater damaged and light output reduced

MOT #3 2018-03-29 12:34**MOT test number** 720742907138**Result** ✓ Passed

- Advice** Slight damage offside front indicator side repeater

MOT #2 2018-03-26 11:14**MOT test number** 580018922678**Result** ✗ Failed

- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Slight damage offside front indicator side repeater

MOT #1 2016-04-26 10:06**MOT test number** 546582534527**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
18 April 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-07-31
Last registration	2024-04-15
Complete history	See info



Registration #1	2013-07-31	28 mi
Registration #2	2016-04-26	28.104 mi
Registration #3	2018-03-26	44.612 mi
Registration #4	2018-03-29	44.626 mi
Registration #5	2019-04-13	56.029 mi
Registration #6	2019-04-13	56.029 mi
Registration #7	2019-04-13	56.029 mi
Registration #8	2019-04-13	56.029 mi
Registration #9	2019-04-13	56.029 mi
Registration #10	2019-04-13	56.029 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1570 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4155832