



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Red
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 2

Date	2021-09-29
Pictures	3
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-28
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-05
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	11
Total items failed	9

MOT #18	2022-09-30 16:12
MOT test number	424749130956
Result	✓ Passed
Next expiry date	2023-10-05

MOT #17	2022-09-30 15:32
MOT test number	414607074281
Result	✗ Failed
Fail	Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Emissions not tested (8.2.1.2 (d))

MOT #16	2021-10-06 08:42
MOT test number	618171444165
Result	✓ Passed

MOT #15	2021-10-06 08:42
MOT test number	190139985238
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #14** 2020-09-10 11:29**MOT test number** 842039917623**Result** ✓ Passed**MOT #13** 2020-09-09 10:30**MOT test number** 668904005059**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2019-09-03 11:51**MOT test number** 823775041913**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing 175-65-15 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and has a nail in 175-65-15 (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing 175-65-15 (5.2.3 (d) (ii))**Advice** Offside handbrake reading lower than nearside**Advice** Offside Rear Tyre slightly damaged/cracking or perishing and has a nail in 175-65-15 (5.2.3 (d) (ii))**MOT #11** 2018-08-29 10:47**MOT test number** 594632914799**Result** ✓ Passed**MOT #10** 2018-08-29 10:47**MOT test number** 181766908440**Result** ✗ Failed**Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))

**MOT #9** 2017-09-04 10:18**MOT test number** 687286033841**Result** ✓ Passed**MOT #8** 2016-08-15 08:11**MOT test number** 482533076387**Result** ✓ Passed**Advice** Nearside Rear Exhaust box corroded.**MOT #7** 2015-08-27 09:10**MOT test number** 855897302773**Result** ✓ Passed**MOT #6** 2015-08-25 09:16**MOT test number** 804935482225**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2014-09-08 17:32**MOT test number** 205691554223**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)


**MOT #4** 2014-09-08 10:06**MOT test number** 686701454245**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2013-08-30 15:57**MOT test number** 398452643299**Result** ✓ Passed**MOT #2** 2012-08-16 17:17**MOT test number** 416929022265**Result** ✓ Passed**MOT #1** 2011-09-08 09:22**MOT test number** 577781351240**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-03
Last registration	2022-09-30
Complete history	See info



Registration #1	2008-09-03	9 mi
Registration #2	2011-09-08	28.830 mi
Registration #3	2012-08-16	33.104 mi
Registration #4	2013-08-30	40.093 mi
Registration #5	2014-09-08	46.012 mi
Registration #6	2014-09-08	46.014 mi
Registration #7	2015-08-25	48.224 mi
Registration #8	2015-08-27	48.224 mi
Registration #9	2016-08-15	48.407 mi
Registration #10	2017-09-04	49.192 mi
Registration #11	2018-08-29	49.615 mi
Registration #12	2019-09-03	50.000 mi
Registration #13	2020-09-03	50.000 mi
Registration #14	2021-09-03	50.000 mi
Registration #15	2022-09-03	50.000 mi
Registration #16	2023-09-03	50.000 mi
Registration #17	2024-09-03	50.000 mi
Registration #18	2025-09-03	50.000 mi
Registration #19	2026-09-03	50.000 mi
Registration #20	2027-09-03	50.000 mi
Registration #21	2028-09-03	50.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4708035