




report date: 2024-03-29

General information

Make	DACIA
Model	LOGAN AMBIANCE TCE
Colour	White
Year of manufacture	2015
Top speed	109 mph
0 - 100 km/h	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-05-09
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-05-18
<b>MOT pass rate</b>	60 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	16
<b>Total items failed</b>	10

<b>MOT #10</b>	2023-05-17 10:35
<b>MOT test number</b>	311705638060
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-05-18
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #9</b>	2023-05-10 10:18
<b>MOT test number</b>	805530423899
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Fail</b>	Offside Headlamp levelling device inoperative (4.1.5 (a))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Offside Rear Service brake excessively binding (1.2.1 (f))
<b>Fail</b>	Nearside Headlamp levelling device inoperative (4.1.5 (a))
<b>Fail</b>	Offside Headlamp aim too low (4.1.2 (a))

**MOT #8** 2022-05-19 11:22**MOT test number** 157729875193**Result** ✓ Passed**MOT #7** 2022-05-18 13:03**MOT test number** 344406838121**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2021-11-01 09:32**MOT test number** 764266634930**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2021-10-27 08:30**MOT test number** 457675087142**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #4** 2020-08-20 09:48**MOT test number** 425765046278**Result** ✓ Passed

**MOT #3** 2019-03-14 13:13**MOT test number** 463673651942**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2018-03-16 11:45**MOT test number** 636355220196**Result** ✓ Passed**Advice** Rear foot brake just met the brake imbalance of 30%**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under trays fitted**MOT #1** 2018-03-16 11:45**MOT test number** 708753716682**Result** ✗ Failed**Advice** Rear foot brake just met the brake imbalance of 30%**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Under trays fitted**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
18 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	18 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this DACIA. See if, where and when this DACIA had damage and the car repair costs. We also check if this DACIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra DACIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this DACIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this DACIA? How many owners did this DACIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this DACIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this DACIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DACIA has been settled.

If not, and you buy this DACIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this DACIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-20
Last registration	2023-05-17
Complete history	<a href="#">See info</a>



Registration #1	2015-03-20	22 mi
Registration #2	2018-03-16	26.567 mi
Registration #3	2018-03-16	26.567 mi
Registration #4	2019-03-14	44.426 mi
Registration #5	2020-08-20	72.720 mi
Registration #6	2021-10-27	94.218 mi
Registration #7	2023-05-17	115.277 mi
Registration #8	2023-05-17	115.277 mi
Registration #9	2023-05-17	115.277 mi
Registration #10	2023-05-17	115.277 mi
Registration #11	2023-05-17	115.277 mi
Registration #12	2023-05-17	115.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1733 mm
Height	1550 mm
Length	4492 mm
Wheel base	2634 mm
Kerb weight	1038 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	U260244