



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Blue
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-06-20
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	40
Total items failed	5

MOT #15 2023-09-26 15:18

MOT test number 793293561014

Result ✓ Passed

Next expiry date 2024-09-25

Minor Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i))

MOT #14 2022-07-16 14:08

MOT test number 706415893056

Result ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

Advice Rear exhaust box corroded

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13**

2022-07-16 14:08

MOT test number

711002486900

Result**✗ Failed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Rear exhaust box corroded**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Front Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**MOT #12**

2022-06-17 09:06

MOT test number

466120296860

Result**✗ Failed****DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn thin (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Brake fluid contaminated (1.8 (a))

**MOT #11** 2021-05-24 09:08**MOT test number** 772022507365**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #10** 2020-06-10 12:47**MOT test number** 154921790462**Result** ✓ Passed**MOT #9** 2020-06-02 10:51**MOT test number** 690433643806**Result** ✗ Failed**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Side repeater missing (4.4.1 (a) (ii))**MOT #8** 2019-05-02 17:48**MOT test number** 307139587249**Result** ✓ Passed**MOT #7** 2018-05-12 13:35**MOT test number** 476074831482**Result** ✓ Passed

**MOT #6** 2016-09-02 09:01**MOT test number** 309000219686**Result** ✓ Passed**Advice** Engine light on**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-12 10:08**MOT test number** 225691975059**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-03-12 10:08**MOT test number** 969831475071**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-14 13:24**MOT test number** 286853374059**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre



MOT #2	2013-02-26 10:37
MOT test number	415947053019
Result	✓ Passed
<div>Advice</div> Parking brake lever has little reserve travel (3.1.6b)	

MOT #1	2012-03-02 16:18
MOT test number	137982762483
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	EX09PHA
Plate since	2024-03-29
Current registration	EX09PHA
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-02
Last registration	2023-09-26
Complete history	See info



Registration #1	2009-03-02	8 mi
Registration #2	2012-03-02	19.132 mi
Registration #3	2013-02-26	36.551 mi
Registration #4	2014-03-14	52.964 mi
Registration #5	2015-03-12	56.891 mi
Registration #6	2016-09-02	64.152 mi
Registration #7	2018-05-12	71.994 mi
Registration #8	2019-05-02	75.431 mi
Registration #9	2020-05-02	75.431 mi
Registration #10	2020-05-02	75.431 mi
Registration #11	2020-05-02	75.431 mi
Registration #12	2020-05-02	75.431 mi
Registration #13	2020-05-02	75.431 mi
Registration #14	2020-05-02	75.431 mi
Registration #15	2020-05-02	75.431 mi
Registration #16	2020-05-02	75.431 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BZG258667