





report date: 2024-03-29

General information

Make	HYUNDAI
Model	AMICA GSI
Colour	Red
Year of manufacture	2007
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date	2022-01-18
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-08-07
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #20	2023-08-08 07:38
MOT test number	200520401590
Result	✓ Passed
Next expiry date	2024-08-07

MOT #19	2023-07-25 09:51
MOT test number	383280411112
Result	X Failed
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Driver's door cannot be opened from outside the vehicle (6.2.3 (a))	

MOT #18	2022-10-03 13:07
MOT test number	116778909055
Result	✓ Passed

MOT #17	2022-10-01 11:49
MOT test number	289408172146
Result	X Failed
Fail Offside Front Inner Tyre has ply or cords exposed edge (5.2.3 (d) (ii))	
Fail Nearside Front Windscreen wiper does not clear the windscreen effect	ctively (3.4 (b) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

 MOT #14
 2020-10-29 13:36

 MOT test number
 811452635005

 Result
 ✓ Passed

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside rear tyre sidewall damage

Advice Rear tyres cracking

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Failed

Advice Offside rear tyre sidewall damage

Advice Child Seat fitted not allowing full inspection of adult belt

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear tyres cracking

MOT #11 2018-10-10 13:32 **MOT** test number 235519812495 Result Passed **Advice** Nearside rear tyre cracking in tread Advice Child Seat fitted not allowing full inspection of adult belt Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm bald inner edge and cracking (5.2.3 (e)) Advice Offside rear tyre side wall damage Advice Items removed from driver's view prior to test

MOT #10	2017-10-30 09:27
MOT test number	579240118650
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #9		2017-10-25 08:46
MOT test	number	971554460575
Result		🗙 Failed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Fail No	earside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

2017-06-24 08:47
633200152378
✓ Passed
2016-06-18 08:07
411706700534
✓ Passed
2015-06-15 13:49
916236565148
✓ Passed
2014-06-09 10:12
2014-06-09 10:12 786400764134
786400764134
786400764134
786400764134 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3	2012-06-07 08:58
MOT test number	638329152164
Result	✓ Passed
MOT #2	2011-05-18 08:58
MOT test number	799628131176
Result	✓ Passed
MOT #1	2010-06-02 12:25
MOT test number	261523050455
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-14
Last registration	2023-08-08
Complete history	See info



Registration #1	2007-06-14	29 mi
Registration #2	2010-06-02	4.539 mi
Registration #3	2011-05-18	5.793 mi
Registration #4	2012-06-07	6.976 mi
Registration #5	2013-05-31	7.989 mi
Registration #6	2014-06-09	8.447 mi
Registration #7	2015-06-15	8.490 mi
Registration #8	2016-06-18	8.499 mi
Registration #9	2017-06-24	19.866 mi
Registration #10	2017-10-25	24.430 mi
Registration #11	2017-10-30	24.430 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 13/14



DN07XUP report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	932 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	G4HG6M024294

CarCheck.co.uk page 14/14