



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Red
Year of manufacture	2004
Top speed	107 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-20
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2022-08-30
<b>MOT pass rate</b>	70 %
<b>MOT passed</b>	16
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	60
<b>Total items failed</b>	11

<b>MOT #23</b>	2021-08-31 14:47
<b>MOT test number</b>	936713410613
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-30
<b>Advice</b>	Centre exhaust bracket broken
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #22</b>	2020-08-19 10:16
<b>MOT test number</b>	669988258306
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #21**

2019-08-16 10:22

**MOT test number**

190124353842

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #20**

2019-08-09 10:34

**MOT test number**

286746240328

**Result**

✗ Failed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19** 2018-08-29 12:30**MOT test number** 319029758839**Result** ✓ Passed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front brake discs worn

**MOT #18** 2018-08-20 14:25**MOT test number** 972418940499**Result** ✗ Failed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front brake discs worn
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #17** 2018-05-14 08:10**MOT test number** 389792052401**Result** ✗ Failed

- Advice** Slight Oil Leak from top of Engine
- Fail** Nearside Front Headlamp aim beam image obviously incorrect Headlamp Lens Deteriorated (1.8.A.1b)
- Advice** Front and Rear Brake Discs Corroded / Worn
- Fail** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Front and Rear Brake Pads Getting Low
- Fail** Offside Front Headlamp aim beam image obviously incorrect Headlamp Lens Deteriorated (1.8.A.1b)

**MOT #16** 2017-05-09 12:14**MOT test number** 474086461680**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Engine covers fitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays fitted**MOT #15** 2016-04-27 08:58**MOT test number** 947447034815**Result** ✓ Passed**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #14** 2015-05-07 15:43**MOT test number** 475437625140**Result** ✓ Passed**Notice** Brake pedal anti slip pad wearing on edge**Notice** Both headlamps beam patterns just in specification

**MOT #13** 2015-05-07 15:43**MOT test number** 448097525192**Result** ✗ Failed**Notice** Both headlamps beam patterns just in specification**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Brake pedal anti slip pad wearing on edge**MOT #12** 2014-04-23 09:31**MOT test number** 829313014157**Result** ✓ Passed**Advice** Offside Steering system has slight free play detected at steering wheel (2.2.A.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres have uneven wear**Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1a)**MOT #11** 2013-05-01 15:18**MOT test number** 815601423127**Result** ✓ Passed**MOT #10** 2013-05-01 15:18**MOT test number** 368541723197**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2012-05-10 08:10**MOT test number** 749681032105**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs slightly worn**Notice** Offside front tyre outer sidewall damaged (cords not showing)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-05-04 17:03**MOT test number** 137365822182**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside front tyre outer sidewall damaged (cords not showing)**Notice** Front brake discs slightly worn**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-05-09 13:26**MOT test number** 175579421171**Result** ✓ Passed**MOT #6** 2010-06-04 08:59**MOT test number** 460405150140**Result** ✓ Passed



**MOT #5** 2009-06-17 15:22**MOT test number** 373648269134**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #4** 2009-06-17 15:22**MOT test number** 523618269134**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Nail in nearside rear tyre**MOT #3** 2008-10-13 16:59**MOT test number** 913197988209**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Steering rack worn nearside**MOT #2** 2007-10-23 14:56**MOT test number** 661146097233**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2007-01-04 11:53**MOT test number** 520484707061**Result** ✓ Passed



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-01-30
Last registration	2021-08-31
Complete history	<a href="#">See info</a>



Registration #1	2004-01-30	10 mi
Registration #2	2007-01-04	29.333 mi
Registration #3	2007-10-23	31.365 mi
Registration #4	2008-10-13	35.782 mi
Registration #5	2009-06-17	39.297 mi
Registration #6	2010-06-04	42.845 mi
Registration #7	2011-05-09	46.747 mi
Registration #8	2012-05-04	54.842 mi
Registration #9	2012-05-10	55.021 mi
Registration #10	2013-05-01	61.604 mi
Registration #11	2014-04-23	68.502 mi
Registration #12	2015-05-20	75.377 mi
Registration #13	2016-05-20	82.252 mi
Registration #14	2017-05-20	89.127 mi
Registration #15	2018-05-20	96.002 mi
Registration #16	2019-05-20	102.877 mi
Registration #17	2020-05-20	109.752 mi
Registration #18	2021-05-20	116.627 mi
Registration #19	2022-05-20	123.502 mi
Registration #20	2023-05-20	130.377 mi
Registration #21	2024-05-20	137.252 mi
Registration #22	2025-05-20	144.127 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D089071