





report date: 2024-03-28

General information

Make	CITROEN
Model	C1 FEEL
Colour	White
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-02-01
B: 1	1.0

Pictures 16

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MV67AKZ report date: 2024-03-28

MOT history

MOT expiry date	2025-03-08
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	25
Total items failed	0

MOT #6		2024-03-09 11:37
MOT test	number	315161782088
Result		✓ Passed
Next expi	ry date	2025-03-08
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply	or cords (5.2.3 (d) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both	(1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5		2023-03-08 12:45
MOT test	number	257037794349
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exc	cessive movement
(5.3.4 (a) (i))	
Advice	Offside Rear Nail in tyre	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exce	essive movement (5.3.4
(a) (i))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2023-03-08 10:53 553188168892 **MOT test number** Result × Failed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Rear Nail in tyre

MOT #3		2022-03-02 10:06
MOT test	number	599644387429
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2022-03-02 10:00
MOT test	number	857000486042
Result		× Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2020-12-08 09:58
MOT test	number	531234145068
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

MV67AKZ

report date: 2024-03-28

UK UK

More info >

Owner history		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		ROEN
HARMAN AND AND AND AND AND AND AND AND AND A		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



MV67AKZ report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-12-12
Last registration	2024-03-09
Complete history	See info



Registration #1	2017-12-12	18 mi
Registration #2	2020-12-08	24.126 mi
Registration #3		11.777 es
Registration #4		0.00 44
Registration #5	2022-03-02	28.042 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	大大大大大
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	855 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	8275221

CarCheck.co.uk page 12/12