



General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Grey
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-12-17
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	56
Total items failed	12

MOT #18	2023-12-18 16:04
MOT test number	997217814354
Result	✓ Passed
Next expiry date	2024-12-17
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Tyre worn close to legal limit/worn on edge both inner edges (5.2.3 (e))

MOT #17	2022-12-02 13:25
MOT test number	220902925964
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Coil spring corroded Nearside and Offside (5.3.1 (b) (i))

**MOT #16**

2021-12-08 13:13

MOT test number

481514129302

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

MOT #15

2020-12-09 10:45

MOT test number

989384234611

Result

✓ Passed

- Minor** Nearside Rear Position lamp light intensity obviously reduced some leds out (4.2.3 (a) (i))
- Minor** Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning leds out (4.4.1 (a) (i))
- Minor** Offside Rear Position lamp light intensity obviously reduced some leds out (4.2.3 (a) (i))
- Minor** Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning leds out (4.4.1 (a) (i))

MOT #14

2020-12-08 11:52

MOT test number

103053002237

Result

✓ Passed

MOT #13

2020-07-03 13:42

MOT test number

200497239785

Result

✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2020-07-03 08:53

MOT test number

938816166372

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11

2019-07-31 12:48

MOT test number

680203315637

Result**✓ Passed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Minor** Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Nearside Front Inner Brake pad(s) wearing thin inner pad wearing low (1.1.13 (a) (ii))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-07-31 11:56

MOT test number

875982670558

Result**✗ Failed****Advice** Nearside Front Inner Brake pad(s) wearing thin inner pad wearing low (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm tyre below legal limit on inner edge (5.2.3 (e))**Fail** Nearside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm tyre below legal limit on inner edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Fail** Offside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))**Fail** Nearside Rear Direction indicator with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))**MOT #9**

2018-06-16 10:59

MOT test number

326130774939

Result**✓ Passed****Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**MOT #8**

2018-06-16 07:27

MOT test number

385534560681

Result**✗ Failed****Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7**

2017-06-23 11:43

MOT test number

870027778620

Result**✓ Passed****Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Emissions too low to record**MOT #6**

2017-06-23 11:43

MOT test number

976680444635

Result**✗ Failed****Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Emissions too low to record**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5**

2016-07-12 11:04

MOT test number

875857308391

Result**✓ Passed****Advice** Rear Child Seat fitted not allowing full inspection of adult belt



MOT #4	2015-06-19 09:16
MOT test number	496540675158
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3	2014-06-17 09:07
MOT test number	327828564124
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Under-trays fitted obscuring some underside components
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Engine management light on

MOT #2	2014-06-17 09:07
MOT test number	909308264191
Result	✗ Failed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Engine management light on
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Under-trays fitted obscuring some underside components



MOT #1	2013-06-04 16:01
MOT test number	716705353108
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 December 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-28
Last registration	2023-12-18
Complete history	See info



Registration #1	2010-06-28	6 mi
Registration #2	2013-06-04	20.530 mi
Registration #3	2014-06-17	29.423 mi
Registration #4	2015-06-19	37.085 mi
Registration #5	2016-07-12	49.689 mi
Registration #6	2017-06-23	63.978 mi
Registration #7	2017-06-23	63.978 mi
Registration #8	2018-06-16	78.109 mi
Registration #9	2018-06-16	78.109 mi
Registration #10	2019-07-31	94.189 mi
Registration #11	2019-06-28	94.189 mi
Registration #12	2019-06-28	94.189 mi
Registration #13	2019-06-28	94.189 mi
Registration #14	2019-06-28	94.189 mi
Registration #15	2019-06-28	94.189 mi
Registration #16	2019-06-28	94.189 mi
Registration #17	2019-06-28	94.189 mi
Registration #18	2019-06-28	94.189 mi
Registration #19	2019-06-28	94.189 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 371263