





report date: 2024-03-29

#### General information

Make	FIAT
Model	500X MULTIJET CROSS
Colour	Grey
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

N/I	$\alpha$		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-10-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	0

MOT #9	2023-10-03 15:37
MOT test number	528335874818
Result	✓ Passed
Next expiry date	2024-10-19

MOT #8		2023-10-03 09:01
MOT test	number	396354567781
Result		<b>X</b> Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #7		2022-10-11 16:26
MOT test i	number	997996341959
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge slightly worn on edge	es (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2021-10-08 16:25

**MOT test number** 518846935108

MOT #5 2021-10-08 08:35

**MOT test number** 991111848510

Result X Failed

MAJOR Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #4 2020-10-20 15:42

**MOT test number** 442720688649

MOT #3 2020-10-16 09:53

**MOT test number** 295955881978

**Result** X Failed

**DANGEROUS** Nearside Front Outer Tyre has a tear, caused by separation or partial failure of its structure 225/45/18, worn inner and outer on limit 2.00mm (5.2.3 (d) (ii))

**DANGEROUS** Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure 225/45/18, on limit at 2.00mm worn inner and outer, (5.2.3 (d) (ii))

MOT #2 2019-05-08 08:59

**MOT test number** 719089494829

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #1** 2018-05-03 10:37

**MOT test number** 791469872050

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Nail in tyre

**Advice** DPF fitted no reading

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	19 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK NK
Plate since	
Current registration	OK STE
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-08
Last registration	2023-10-03
Complete history	See info



Registration #1	2015-05-08	13 mi
Registration #2	2018-05-03	7.762 mi
Registration #3	2019-05-08	11.643 mi
Registration #4	2020-10-16	17.022 mi
Registration #5	2020-10-20	17.022 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

# Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles2Engine number7511554