

Ford



## General information

Make	FORD
Model	MONDEO ZETEC 16V
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	123 BHP
Max. torque	170 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg





# Internet history

Entry 1	
Date	2021-06-06
Pictures	11
Listing price	View report









source: autotrader.co.uk



# MOT history

MOT #19	2023-05-24 11:45
MOT test number	184324348179
Result	✓ Passed
Next expiry date	2024-05-23

MOT #18	2022-05-13 09:33
MOT test number	685518459155
Result	✓ Passed
Minor Headlamp lens slightly defective both (4.1.1 (b) (i))	

MOT #17	2022-05-13 09:33	
MOT test number	355744442675	
Result	× Failed	
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Minor Headlamp lens slightly defective both (4.1.1 (b) (i))		
<b>Pass with rectification</b> Offside Rear Macpherson strut attachment bracket/mounting insecure and impairing directional stability (5.3.3 (a) (ii))		

MOT #16	2022-01-13 13:46
MOT test number	591227254816
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





2021-01-22 09:51 231648862857

MOT #15		2021-01-25 16:34
MOT test	number	160408260353
Result		✓ Passed
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	

# MOT #14

мот	test	number	
-----	------	--------	--

Result	🗙 Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
<b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
FailRear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	

MOT #13	2020-01-20 09:59
MOT test number	932307266004
Result	✓ Passed
Advice Both front tyres worn on inner treads	

MOT #12	2019-01-17 12:50
MOT test number	568048222023
Result	✓ Passed





MOT #11	2018-01-22 09:09
MOT test number	549843032015
Result	✓ Passed
MOT #10	2017-01-06 10:45
MOT test number	411403962123
Result	✓ Passed

МОТ #9	2016-01-25 10:10
MOT test number	214970052006
Result	✓ Passed
Advice Front tyres wearing low on tread	

MOT #8		2015-01-23 10:18
MOT test	number	256723625006
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #7	2014-01-21 14:15
MOT test number	255091424068
Result	✓ Passed
МОТ #6	2013-01-24 09:42
MOT test number	369394523075
Result	✓ Passed
MOT #5	2012-01-25 09:54

MOT test number	156365722449
Result	✓ Passed





MOT #4	2011-01-13 14:46
MOT test number	765933511093
Result	✓ Passed
MOT #3	2010-01-25 09:32
MOT test number	434825820097
Result	✓ Passed

MOT #2		2009-01-27 11:36
MOT test	number	784937029043
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2008-01-02 14:14
MOT test number	422342708053
Result	✓ Passed
Advice Front Tyre worn close to the legal limit (4.1.E.1)	





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	F Store
Date	1.E
Category	AMP
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-09
Last registration	2023-05-24
Complete history	See info



Registration #1	2005-01-09	9 mi
Registration #2	2008-01-02	24.705 mi
Registration #3	2009-01-27	30.736 mi
Registration #4	2010-01-25	36.345 mi
Registration #5	2011-01-13	42.614 mi
Registration #6	2012-01-25	48.024 mi
Registration #7	2013-01-24	51.810 mi
Registration #8	2014-01-21	59.500 mi
Registration #9	2015-01-23	65.300 mi
Registration #10	2016-01-25	71.471 mi
Registration #11	2017-01-06	78.216 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		0.300 mi
Registration #20		11.777 est
Registration #21		11.227 esi

More info >





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**Number of seats** 

Number of axles

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1931 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1388 kg
Max. allowed weight	1910 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5

5

2