





General information VAUXHALL Make Model CORSA SRI VX-LINE NAV BLACK SRI VX-LINE NAV BLACK S/S Colour Grey Year of manufacture 2019 **Top speed** 109 mph 0 - 60 mph 13.2 seconds Gearbox 5 speed Manual

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2022-04-02 |
| Pictures | 37 |
| Listing price | View report |





source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-06-12 16 <u>View report</u>



source: autotrader.co.uk







SS VYH



MOT history

| MOT expiry date | 2025-04-04 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #3 | 2024-03-28 14:45 |
|--|------------------|
| MOT test number | 481686616288 |
| Result | 🗸 Passed |
| Next expiry date | 2025-04-04 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #2 | 2023-03-28 10:42 |
|--|------------------|
| MOT test number | 790273681678 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii)) | |
| | |

| MOT #1 | 2022-04-05 14:27 |
|-----------------|------------------|
| MOT test number | 872546418843 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 April 2025 | ✓ MOT Expires: 4 April 2025 |
|--|--------------------------------------|
| Tax status | Valid until 1 April |
| Days left | 337 |
| MOT expiry date | 4 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET A |
| Category | L AMP |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|---|-------------|
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| | |
| Plate since | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-09-30 |
| Last registration | 2024-03-28 |
| Complete history | See info |
| | |



| Registration #1 | 2019-09-30 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | | 11.777 est |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 est |





Safety ratings

| NCAP rating | **** | ۵ (|
|----------------|------------------------|-----|
| Adult | 87% | S |
| Children | 72% | |
| Pedestrian | 65% | |
| Safety systems | 81% | |
| Overall rating | 79% | - |
| Video | <u>see crash video</u> | |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1746 mm |
| Height | 1481 mm |
| Length | 4021 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1176 kg |
| Max. allowed weight | 1630 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 45 l |
| | 45 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |