



report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Grey
Year of manufacture	-
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN

**MOT history**

MOT #25	2020-10-06 06:49
MOT test number	862884971371
Result	✓ Passed
Next expiry date	2021-10-10
Advice	Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Advice	No reverse light
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Central Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))

MOT #24	2020-10-06 06:49
MOT test number	178630589931
Result	✗ Failed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Play in steering rack inner joint(s)
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	No reverse light
Advice	Central Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))
Advice	Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #23**

2019-10-01 13:41

MOT test number

791410943084

Result

✓ Passed

Advice High level brake light not working**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Play in steering rack inner joint(s)**MOT #22**

2019-10-01 06:44

MOT test number

695488828655

Result

✗ Failed

Advice Nearside Play in steering rack inner joint(s)**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** High level brake light not working**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #21**

2018-10-11 07:51

MOT test number

350972732640

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing in tread pattern (5.2.3 (d) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Nearside front tyre wearing outer edge

**MOT #20**

2018-10-11 07:51

MOT test number

179753564076

Result**✗ Failed****Advice** Play in steering rack inner joint(s)**Pass with rectification** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside front tyre wearing outer edge**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing in tread pattern (5.2.3 (d) (ii))**MOT #19**

2017-09-11 14:17

MOT test number

345392302128

Result**✓ Passed****Advice** Centre stop light not working**Advice** Nearside beam output reduced slightly**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #18**

2017-09-11 10:03

MOT test number

890869396295

Result**✗ Failed****Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside beam output reduced slightly**Fail** Brake pipe excessively corroded both front to rear [rear sections] (3.6.B.2c)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Centre stop light not working**MOT #17**

2016-09-28 11:33

MOT test number

590360800739

Result**✓ Passed**

**MOT #16** 2016-09-28 09:52**MOT test number** 476025509321**Result** ✗ Failed

Fail Nearside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)

MOT #15 2015-10-09 12:15**MOT test number** 630523171927**Result** ✓ Passed

Advice Nearside front tyre wearing outer edge

Advice Offside rear tyre wall scuffed and cracked

MOT #14 2015-10-09 09:05**MOT test number** 701785562450**Result** ✗ Failed

Fail Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice Nearside front tyre wearing outer edge

Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)

Advice Offside rear tyre wall scuffed and cracked

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #13 2014-10-04 10:10**MOT test number** 378187674254**Result** ✓ Passed

**MOT #12** 2013-10-01 16:57**MOT test number** 998504173257**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2013-10-01 16:57**MOT test number** 185384773228**Result** ✗ Failed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2012-10-03 10:23**MOT test number** 949607472279**Result** ✓ Passed**MOT #9** 2012-09-29 15:17**MOT test number** 985983972286**Result** ✗ Failed**Fail** Offside Front Brake hose bulging under pressure (3.6.B.3)**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #8** 2012-01-17 11:24**MOT test number** 156107912479**Result** ✓ Passed

**MOT #7** 2010-12-15 15:33**MOT test number** 192289040351**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2010-12-15 15:33**MOT test number** 892069540339**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-12-03 11:30**MOT test number** 490407139319**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-11-28 12:05**MOT test number** 680903938387**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #3** 2008-11-28 12:05**MOT test number** 651773338368**Result** ✓ Passed



MOT #2	2007-11-30 09:01
MOT test number	720274737313
Result	✓ Passed
Advice	Offside Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #1	2007-02-19 10:47
MOT test number	690170057025
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-02-27
Last registration	2020-10-06
Complete history	See info



Registration #1	2004-02-27	22 mi
Registration #2	2007-02-19	29.900 mi
Registration #3	2007-11-30	37.611 mi
Registration #4	2008-11-28	45.488 mi
Registration #5	2009-12-03	53.304 mi
Registration #6	2010-12-15	58.265 mi
Registration #7	2012-01-17	64.273 mi
Registration #8	2012-09-29	69.665 mi
Registration #9	2012-10-03	69.888 mi
Registration #10	2013-10-01	82.674 mi
Registration #11	2014-10-04	86.087 mi
Registration #12	2015-10-09	89.154 mi
Registration #13	2016-10-09	92.221 mi
Registration #14	2017-10-09	95.288 mi
Registration #15	2018-10-09	98.355 mi
Registration #16	2019-10-09	101.422 mi
Registration #17	2020-10-09	104.489 mi
Registration #18	2021-10-09	107.556 mi
Registration #19	2022-10-09	110.623 mi
Registration #20	2023-10-09	113.690 mi
Registration #21	2024-10-09	116.757 mi
Registration #22	2025-10-09	119.824 mi
Registration #23	2026-10-09	122.891 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1157 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4B53843