



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-07-10
Pictures	17
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-07-08
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	17
Total items failed	20

MOT #12	2024-03-14 10:48
MOT test number	926033973189
Result	✓ Passed
Next expiry date	2025-03-13
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11	2024-03-14 10:48
MOT test number	626786071847
Result	✗ Failed
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))

**MOT #10**

2023-04-17 09:11

MOT test number

346974963652

Result

✓ Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9**

2023-04-14 08:02

MOT test number

414384325958

Result

✗ Failed

Fail Offside Rear Brake pipe at imminent risk of failure or fracture Bracket bent resulting in brake pipe fouling vehicle (1.1.11 (a))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Headlamp aim unable to be tested Bulb inoperative (4.1.2 (b))**Fail** Rear Rear fog lamp adversely affected by the operation of another lamp Unable to turn fog lights off once activated (4.5.4 (b))**MOT #8**

2022-04-14 12:19

MOT test number

772582766916

Result

✓ Passed

**MOT #7** 2022-04-14 11:42**MOT test number** 625505030051**Result** ✗ Failed**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Front Headlamp incorrect colour (4.1.4 (a))**Fail** Horn not working (7.7 (a))**MOT #6** 2021-09-06 10:19**MOT test number** 511123877346**Result** ✓ Passed**MOT #5** 2020-10-01 12:18**MOT test number** 366996353910**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2020-10-01 11:57**MOT test number** 258458327941**Result** ✗ Failed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3** 2019-12-23 16:16**MOT test number** 490499708592**Result** ✓ Passed



MOT #2	2019-12-23 14:05
MOT test number	287565402272
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #1	2018-12-05 10:41
MOT test number	968025342685
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-12-10
Last registration	2024-03-14
Complete history	See info



Registration #1	2015-12-10	22 mi
Registration #2	2018-12-05	76.186 mi
Registration #3	2019-12-23	89.590 mi
Registration #4	2019-12-23	89.590 mi
Registration #5	2020-10-01	96.873 mi
Registration #6	2020-10-01	96.873 mi
Registration #7	2020-10-01	96.873 mi
Registration #8	2020-10-01	96.873 mi
Registration #9	2020-10-01	96.873 mi
Registration #10	2020-10-01	96.873 mi
Registration #11	2020-10-01	96.873 mi
Registration #12	2020-10-01	96.873 mi
Registration #13	2020-10-01	96.873 mi
Registration #14	2020-10-01	96.873 mi
Registration #15	2020-10-01	96.873 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZG4158506