





report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER D
Colour	Grey
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2021-10-06

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



AE63SGO report date: 2024-03-29

MOT history

MOT expiry date	2024-11-07
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	7
Total items failed	3

MOT #9	2023-11-08 16:53
MOT test number	297889805824
Result	✓ Passed
Next expiry date	2024-11-07
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #8	2023-11-08 14:04
MOT test number	911150478725
Result	X Failed
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #7	2022-10-18 09:05
MOT test number	348103557455
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6	2021-10-0	8 23:03
MOT test	t number 583025	741656
Result	✓	Passed
Advice Offside Tyre has a cut but not deep enough to reach the ply or cords intread (5.2.3 (d) (i))		
Advice Central Rear brake lamp inop		
Minor	Offside Front Inner Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #5	2020-08-18 08:12
MOT test number	353062277908
Result	✓ Passed
MOT #4	2019-08-31 08:40
MOT test number	661021121213
Result	✓ Passed
MOT #3	2018-08-21 09:48
MOT test number	136108255005
Result	✓ Passed
MOT #2	2017-08-22 09:08

MOT #2	2017-08-22 09:08
MOT test number	138016723801
Result	✓ Passed

MOT #1		2016-08-17 11:18
MOT test	number	766422041239
Result		✓ Passed
Advice	Offside Rear Nail in tyre	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	3.3.1d)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this MINI? How many owners did check it in the premium report and see all owner registrations. Download the full report		e?

HEREE STATE OF THE		
THE STATE OF THE S		

THE STREET STREE		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-09-04
Last registration	2023-11-08
Complete history	See info



Registration #1	2013-09-04	15 mi
Registration #2	2016-08-17	24.385 mi
Registration #3	2017-08-22	29.000 mi
Registration #4	2018-08-21	37.418 mi
Registration #5	2019-08-31	46.973 mi
Registration #6	2020-08-18	53.705 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		19.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1996 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Kerb weight	1300 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11