





report date: 2024-03-28

## General information

| Make                | VOLKSWAGEN     |
|---------------------|----------------|
| Model               | TOURAN S TDI   |
| Colour              | Black          |
| Year of manufacture | 2011           |
| Top speed           | 114 mph        |
| 0 - 100 km/h        | 12.8 seconds   |
| 0 - 60 mph          | 12.8 seconds   |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 77 kW / 105 HP / 106 BHP |
|-------------------------|--------------------------|
| Max. torque             | 250 Nm at 1.500 rpm      |
| Engine capacity         | 1.598 сс                 |
| Cylinders               | 4                        |
| Fuel type               | Diesel                   |
| Consumption city        | 44.8 mpg                 |
| Consumption extra urban | 62.8 mpg                 |
| Consumption combined    | 6.3 mpg                  |
| CO2 emission            | 134 g/km                 |
| CO2 label               | Е                        |



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date 2021-07-02

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

| MOT expiry date    | 2024-08-05 |
|--------------------|------------|
| MOT pass rate      | 91 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 1          |
| Total advice items | 19         |
| Total items failed | 1          |

| MOT #11   | 2023-08-01 12:56 |  |
|---|------------------|--|
| MOT test number   | 259916911962     |  |
| Result  | ✓ Passed         |  |
| Next expiry date 2024-08-0  |                  |  |
| Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |                  |  |

| MOT #10   | 2022-08-05 16:39 |
|---|------------------|
| MOT test number   | 948419140909     |
| Result  | <b>✓</b> Passed  |
|   |                  |
| MOT #9  | 2021-07-21 10:41 |
| MOT test number   | 662261392216     |
| Result  | <b>✓</b> Passed  |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #8          | 2020-08-06 11:58   |
|-----------------|--|
| MOT test        | number 485558479230  |
| Result          | ✓ Passed   |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4    |
| Advice (i))     | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |

CarCheck.co.uk page 3/12



MOT #7

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #6

2018-04-30 15:41

MOT test number

975851391596

Result

✓ Passed

MOT #5

2017-04-12 13:37

MOT test number

822617937410

Result

✓ Passed

Advice

Child Seat fitted not allowing full inspection of adult belt

| MOT #4   |  | 2016-04-18 08:27 |
|----------|--|------------------|
| MOT test | number   | 822065391275     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1) |                  |
| Advice   | Nearside Rear tyre deteriorated                            |                  |
| Advice   | Nearside Front tyre deteriorated                           |                  |

CarCheck.co.uk page 4/12



**MOT** #3 2015-04-17 10:36 **MOT** test number 937087305174 Result ✓ Passed **Notice** Child seat fitted not allowing full inspection of adult belt Notice Engine covers fitted obscuring some components in the engine bay Notice Nearside front tyre on 3mm Notice Offside rear tyre on 3mm and worn on inner edge Notice Under-trays fitted obscuring some underside components Notice Offside front tyre perished Notice Nearside rear tyre starting to perish

MOT #2

MOT test number

429098124089

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 5/12



## Tax & MOT check



| Tax status       | Valid until 1 September |
|------------------|-------------------------|
| Days left        | 126                     |
| MOT expiry date  | 5 August 2024           |
| Full MOT history | See MOT history         |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | Е          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

**Date** 

**Category** 

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

## Owner history

| C Miles Miscory  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. |             |
|  |             |
|  |             |
|  |             |
| **************************************   |             |
| 2000000  |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLKSWAGEN had different number plates.  |             |
| Number of plates   |             |
| Current registration   | AIR<br>WIE  |
| Plate since  |             |
| Current registration   | NK SIK      |
| Plate since  |             |

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2011-03-02 |
| Last registration          | 2023-08-01 |
| Complete history           | See info   |



| Registration #1  | 2011-03-02 | 11 mi     |
|------------------|------------|-----------|
| Registration #2  | 2014-01-28 | 17.904 mi |
| Registration #3  | 2015-04-17 | 25.662 mi |
| Registration #4  | 2016-04-18 | 33.620 mi |
| Registration #5  | 2017-04-12 | 40.018 mi |
| Registration #6  | 2018-04-30 | 44.069 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            |           |

More info >

CarCheck.co.uk page 11/12



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width       | 1794 mm |
|-------------|---------|
| Height      | 1634 mm |
| Length      | 4397 mm |
| Wheel base  | 2678 mm |
| Kerb weight | 1539 kg |

# Additional information

| Fuel tank capacity | 60 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

CarCheck.co.uk page 12/12

| Number of axles | 2 |
|-----------------|---|
|                 |   |

Engine number CAY 586764