




report date: 2024-03-29

General information

Make	VOLVO
Model	V50 E4 D S V50
Colour	Black
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-04
Pictures	48
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-09-05
MOT pass rate	56 %
MOT passed	14
Failed MOT tests	11
Total advice items	11
Total items failed	21

MOT #25 2022-08-30 16:30

MOT test number 300319669078

Result ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #24 2021-09-06 12:25

MOT test number 772464996989

Result ✓ Passed

- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Minor** Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #23** 2021-09-06 12:25**MOT test number** 147301545871**Result** ✗ Failed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Pass with rectification Rear Brake disc in such a condition that it is seriously weakened Both rear (1.1.14 (a) (ii))

MOT #22 2020-07-23 14:47**MOT test number** 415492320952**Result** ✓ Passed**MOT #21** 2020-07-16 11:32**MOT test number** 463087223162**Result** ✗ Failed

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #20 2019-05-17 14:01**MOT test number** 286920873696**Result** ✓ Passed**MOT #19** 2019-05-17 10:57**MOT test number** 946861149150**Result** ✗ Failed

Fail Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #18** 2018-05-23 13:50**MOT test number** 566273674244**Result** ✓ Passed**MOT #17** 2018-05-23 11:39**MOT test number** 151202682593**Result** ✗ Failed**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #16** 2017-05-26 14:02**MOT test number** 677238319671**Result** ✓ Passed**MOT #15** 2017-05-26 10:07**MOT test number** 349358171180**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #14** 2016-05-13 14:38**MOT test number** 613625669376**Result** ✓ Passed**MOT #13** 2016-05-12 09:56**MOT test number** 592645285026**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #12** 2015-05-28 10:35**MOT test number** 537198545186**Result** ✓ Passed**MOT #11** 2015-05-28 10:35**MOT test number** 359558145133**Result** ✗ Failed**Pass with rectification** Rear registration plate insecure (6.3.1b)**MOT #10** 2014-05-16 09:02**MOT test number** 888276534191**Result** ✓ Passed**MOT #9** 2014-05-16 09:02**MOT test number** 239256834475**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2013-06-05 13:47**MOT test number** 138066453127**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear wheel bearing has slight roughness**MOT #7** 2012-06-08 11:24**MOT test number** 776430362130**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-05-18 13:55**MOT test number** 376528331147**Result** ✓ Passed**MOT #5** 2011-05-18 13:55**MOT test number** 937708631118**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2010-06-09 16:55**MOT test number** 183150160124**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-06-04 15:07**MOT test number** 663705659100**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2009-06-04 15:07**MOT test number** 924615059133**Result** ✓ Passed**MOT #1** 2008-06-04 15:30**MOT test number** 754546858123**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 SH05NYG
Plate since	2024-03-29
Current registration	 SH05NYG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-04-25
Last registration	2022-08-30
Complete history	See info



Registration #1	2005-04-25	22 mi
Registration #2	2008-06-04	49.177 mi
Registration #3	2009-06-04	53.108 mi
Registration #4	2010-06-09	56.057 mi
Registration #5	2011-05-18	59.135 mi
Registration #6	2012-06-08	62.728 mi
Registration #7	2013-06-05	65.479 mi
Registration #8	2014-05-16	67.724 mi
Registration #9	2015-05-28	70.344 mi
Registration #10	2016-05-12	72.577 mi
Registration #11	2016-05-13	72.585 mi
Registration #12	2017-05-26	75.532 mi
Registration #13	2018-05-29	78.579 mi
Registration #14	2019-05-29	81.626 mi
Registration #15	2020-05-29	84.673 mi
Registration #16	2021-05-29	87.720 mi
Registration #17	2022-05-29	90.767 mi
Registration #18	2023-05-29	93.814 mi
Registration #19	2024-05-29	96.861 mi
Registration #20	2025-05-29	99.908 mi
Registration #21	2026-05-29	102.955 mi
Registration #22	2027-05-29	106.002 mi
Registration #23	2028-05-29	109.049 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4015751