





report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L2H2 HDI
Colour	White
Year of manufacture	2015
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	ı



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-20

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/12



BC15HHV report date: 2024-03-29

MOT history

MOT expiry date	2024-11-13
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	5

MOT #8	2023-11-10 09:45
MOT test number	532240293479
Result	✓ Passed
Next expiry date	2024-11-13

MOT #7	2022-11-14 11:48
MOT test number	883320766696
Result	✓ Passed

MOT #6	2022-11-09 16:34
MOT test number	468553505289
Result	✓ Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Off side front mirror slightly damaged

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4

MOT test number

Result

Advice Central Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2020-11-06 15:39 780770435083 **MOT** test number Result × Failed Fail Offside Side repeater incorrect colour (4.4.3 (a)) Fail Nearside Side repeater incorrect colour (4.4.3 (a)) Fail Body component damaged and likely to cause injury mirror casing damage (6.2.1 (a) (i)) **Advice** Central Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

 MOT #2
 2019-08-09 14:07

 MOT test number
 582018550530

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2018-08-09 09:26

MOT test number 237814603060

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge 2 mm - 215/70/15C 109/107S (5.2.3 (e))

Advice Slight weap N/S/F inner cv boot clip

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Covers/undertrays fitted

Advice Rear tyres perishing

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

CarCheck.co.uk page 5/12





Tax & MOT check





Expires: 13 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

BC15HHV

report date: 2024-03-29

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN? Check it in the premium report and see all owner registrations. Download the full report here .	ROEN
THE PARTY OF THE P	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY AD	

More info	>

Plate changes

More info >

CarCheck.co.uk page 9/12



BC15HHV report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



BC15HHV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-08-12
Last registration	2023-11-10
Complete history	See info



Registration #1	2015-08-12	26 mi
Registration #2	2018-08-09	52.899 mi
Registration #3	2019-08-09	63.803 mi
Registration #4	2020-11-06	75.262 mi
Registration #5	2020-11-06	75.263 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
-		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 11/12



BC15HHV report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2050 mm
Height	2522 mm
Length	5413 mm
Wheel base	3450 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	TRJA0810982

CarCheck.co.uk page 12/12