





report date: 2024-03-28

General information

Make	MINI
Model	MINI FIRST
Colour	White
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	140 Nm at 2.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-26

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



EY61HWN
report date: 2024-03-28

MOT history

MOT expiry date	2025-04-11
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #13	2024-04-11 11:31
MOT test number	168227489539
Result	✓ Passed
Next expiry date	2025-04-11

MOT #12	2023-03-31 13:22
MOT test number	853997754087
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2023-03-31 13:22
MOT test number	493410343627
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10		2022-04-05 15:09
MOT test nu	ımber	833573848997
Result		✓ Passed
Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9

MOT test number

649329169751

Result

Advice Plastic under covers fitted

MOT #8

MOT test number

746182451477

Result

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT test number

Result

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6

MOT test number

Fesult

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5

MOT test number

Fesult

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4

MOT test number

710945678926

Result

Advice Both rear tyres perishing

MOT #3

MOT test number

648650573468

Result

Advice Nearside Front Road wheel with a slightly distorted bead rim inner (4.2.A.1a)

 MOT #2
 2015-03-17 11:15

 MOT test number
 249406975037

 Result
 ✓ Passed

MOT #1

MOT test number

607032994185

Result

Notice Wipers starting to split

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



funda soloca

EY61HWN

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-28
Last registration	2024-04-11
Complete history	See info



Registration #1	2011-09-28	16 mi
Registration #2	2014-07-11	25.364 mi
Registration #3	2015-03-17	29.942 mi
Registration #4	2016-03-05	38.686 mi
Registration #5	2017-03-03	50.839 mi
Registration #6	2018-03-08	62.799 mi
Registration #7	2019-03-09	76.272 mi
Registration #8	2020-03-16	88.558 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number B626J063