



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA MULTIJET
Colour	Turquoise
Year of manufacture	2013
Top speed	99 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	60.1 mpg
CO2 emission	125 g/km
CO2 label	D






Internet history

Entry 2



Date	2021-02-27
Pictures	25
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-02-26
Pictures	25
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	14

MOT #13	2024-03-07 17:00
MOT test number	347463406641
Result	✓ Passed
Next expiry date	2025-03-08
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12	2024-03-05 11:56
MOT test number	830621503019
Result	✗ Failed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11	2023-03-01 15:29
MOT test number	919340050722
Result	✓ Passed

**MOT #10**

2022-02-22 11:00

MOT test number

840956190233

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #9

2021-03-09 16:38

MOT test number

971619846890

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8

2021-03-08 12:54

MOT test number

888205826494

Result

✗ Failed

Fail

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Windscreen washer not working (3.5 (a))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #7

2020-02-26 14:25

MOT test number

189820505116

Result

✓ Passed

**MOT #6** 2019-05-13 08:41**MOT test number** 319295156616**Result** ✓ Passed**MOT #5** 2019-05-08 10:03**MOT test number** 583895132099**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2018-05-08 09:23**MOT test number** 577201199762**Result** ✓ Passed**MOT #3** 2017-05-15 10:23**MOT test number** 654236879220**Result** ✓ Passed**MOT #2** 2017-05-11 15:04**MOT test number** 789048226028**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)



MOT #1	2016-09-06 10:11
MOT test number	699440290825
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
8 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-09-26
Last registration	2024-03-07
Complete history	See info



Registration #1	2013-09-26	11 mi
Registration #2	2016-09-06	32.902 mi
Registration #3	2017-05-11	34.511 mi
Registration #4	2017-05-15	34.511 mi
Registration #5	2018-05-08	36.631 mi
Registration #6	2019-05-08	38.710 mi
Registration #7	2019-05-13	38.743 mi
Registration #8	2020-02-26	39.531 mi
Registration #9	2020-05-20	39.531 mi
Registration #10	2020-05-20	39.531 mi
Registration #11	2020-05-20	39.531 mi
Registration #12	2020-05-20	39.531 mi
Registration #13	2020-05-20	39.531 mi
Registration #14	2020-05-20	39.531 mi
Registration #15	2020-05-20	39.531 mi
Registration #16	2020-05-20	39.531 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1672 mm
Height	1605 mm
Length	3686 mm
Wheel base	2300 mm
Kerb weight	1190 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4828544