





report date: 2024-03-28

## General information

Make	VOLVO
Model	S90 D4 MOMENTUM
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 3

Date 2021-10-27

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-09-29

Pictures 0

Listing price <u>View report</u>

#### source: heycar.co.uk

#### Entry 1

Date	2021-09-27

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



2022-08-25 11:17

**MOT** history

MOT #3

MOT expiry date	2024-08-28
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #4	2023-08-23 11:47
MOT test number	171119260525
Result	<b>✓</b> Passed
Next expiry date	2024-08-28

MOT test number	875334241188
Result	✓ Passed

**Minor** Front Windscreen damaged but not adversely affecting driver's view 2x chips on front windscreen - not affecting Driver's view (3.2 (a) (i))

MOT #2		2021-08-04 14:48
MOT test	number	575263718699
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Lower Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))		d (5.3.3 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #1 2021-08-04 09:21

**MOT test number** 455999638288

**Result** X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Lower Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	28 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
************	
********	
***************************************	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Correct registration	UK also
Plate since	
Current registration	UK UK
Plate since	
	More info

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-08-29
Last registration	2023-08-23
Complete history	See info



Registration #1	2018-08-29	24 mi
Registration #2	2021-08-04	48.192 mi
Registration #3	2021-08-04	48.211 mi
Registration #4		11.777 es
Registration #5		91.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



# Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

## Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11