



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT TEPEE COMFORT L1 HDI 90 6STR
Colour	Grey
Year of manufacture	2009
Top speed	90 mph
0 - 60 mph	18.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-03
Pictures	2
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-16
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	38
Total items failed	8

MOT #18	2023-06-13 15:16
MOT test number	156800556729
Result	✓ Passed
Next expiry date	2024-06-16
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Rear discs lipped and pads getting low
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Wipers smearing
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2023-06-13 15:16
MOT test number	568361341148
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear discs lipped and pads getting low
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Wipers smearing

**MOT #16**

2022-05-31 15:38

MOT test number

710749207942

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15**

2022-05-31 09:32

MOT test number

625282483730

Result

✗ Failed

MAJOR Offside Front Road wheel badly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Seat belt missing Stalk missing (7.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Rear Road wheel badly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm, cracked & perished (5.2.3 (e))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Power steering fluid level below minimum (2.1.5 (b) (i))**MOT #14**

2021-05-20 13:48

MOT test number

386981023727

Result

✓ Passed

Advice Wheel nuts not fully checked due to covers fitted

**MOT #13**

2021-05-20 13:48

MOT test number

375675190948

Result**✗ Failed****Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Wheel nuts not fully checked due to covers fitted**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #12**

2020-06-17 10:18

MOT test number

795067316738

Result**✓ Passed****Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2020-01-30 13:56

MOT test number

125137428557

Result**✗ Failed****DANGEROUS** Suspension system inoperative air suspension fault light illuminated (5.3.5 (a))**Advice** Nsr light cluster has water ingress**MAJOR** Rear Direction indicator incorrect colour both rear bulbs orange coating worn (4.4.3 (a))**Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**DANGEROUS** Offside Rear Suspension bellows damaged or deteriorated and function is seriously affected (5.3.5 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2019-02-15 11:57**MOT test number** 496782557803**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2018-03-01 11:07**MOT test number** 378739283989**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2018-02-22 12:25**MOT test number** 445450757278**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2017-02-21 11:47**MOT test number** 365182273533**Result** ✓ Passed**MOT #6** 2017-02-17 09:40**MOT test number** 613784987294**Result** ✗ Failed**Fail** Offside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #5** 2016-02-18 11:25**MOT test number** 548719802888**Result** ✓ Passed**MOT #4** 2016-02-17 12:09**MOT test number** 717480461264**Result** ✗ Failed**Advice** Cat heat shields broken**Advice** Oil leak**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #3** 2015-02-16 16:56**MOT test number** 625397045018**Result** ✓ Passed**MOT #2** 2014-02-27 12:38**MOT test number** 175138954465**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-03-01 11:50**MOT test number** 607480163012**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
16 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	16 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	WX59HFN
Plate since	2024-03-29
Current registration	WX59HFN
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-11
Last registration	2023-06-13
Complete history	See info



Registration #1	2009-11-11	16 mi
Registration #2	2013-03-01	15.228 mi
Registration #3	2014-02-27	20.070 mi
Registration #4	2015-02-16	26.031 mi
Registration #5	2016-02-17	30.151 mi
Registration #6	2016-02-18	30.151 mi
Registration #7	2017-02-17	32.747 mi
Registration #8	2017-02-21	32.755 mi
Registration #9	2018-02-22	35.045 mi
Registration #10	2018-03-01	35.045 mi
Registration #11	2019-03-01	35.045 mi
Registration #12	2019-03-01	35.045 mi
Registration #13	2019-03-01	35.045 mi
Registration #14	2019-03-01	35.045 mi
Registration #15	2019-03-01	35.045 mi
Registration #16	2019-03-01	35.045 mi
Registration #17	2019-03-01	35.045 mi
Registration #18	2019-03-01	35.045 mi
Registration #19	2019-03-01	35.045 mi
Registration #20	2019-03-01	35.045 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1998 mm
Height	1934 mm
Length	4806 mm
Wheel base	3000 mm
Max. allowed weight	2683 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	JBBY0016095