





General information

Make	MERCEDES
Model	E E240 AVANTGARDE
Colour	Silver
Year of manufacture	2003
Top speed	142 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.597 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	27.4 mpg
CO2 emission	250 g/km
CO2 label	L







Internet history

Entry 1

Date

2021-10-24

Pictures

Listing price

View report

8



source: cargurus.co.uk

Warranty







MOT history

MOT expiry date	2024-10-18
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	26
Total items failed	5

MOT #19	2023-10-10 13:52
MOT test number	543947001641
Result	✓ Passed
Next expiry date	2024-10-18

MOT #18	2022-09-28 11:02
MOT test number	844893538114
Result	✓ Passed

MOT #17	2021-10-19 14:27
MOT test number	908769190115
Result	✓ Passed

MOT #16	2020-09-15 11:55
MOT test number	877403641279
Result	✓ Passed

MOT #15	2019-09-11 09:48
MOT test number	300520310071
Result	✓ Passed





MOT #14	2018-09-18 09:05
MOT test number	151031323201
Result	✓ Passed
Advice Engine cover and under tray fitted	
MOT #13	2017-09-19 10:52
MOT test number	837263462737
Result	✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle	e within zone 'A' (8.3.1a)
MOT #12	2017-09-14 13:34
MOT test number	372497088565
Result	🗙 Failed
Fail Nearside Front Headlamp excessively deteriorated so that the	light output is severely reduced

(1.7.5a)
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice Offside Front Fog lamp lens broken
Fail Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #11	2016-09-15 13:36
MOT test number	532397875803
Result	✓ Passed
Advice Offside Headlamp deteriorated but light output not reduced output slig make out beam image (1.7.5a)	htly reduced only just
Advice Nearside Headlamp deteriorated but light output not reduced output so make out beam image (1.7.5a)	lightly reduced only just
Advice Service brake warning lamp on	
Advice Windscreen has damage to an area less than a 10mm circle within zon	ie 'A' (8.3.1a)





MOT #10		2015-09-22 10:34
MOT test	number	218835168060
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8	.3.1a)
Advice make out	Nearside Headlamp deteriorated but light output not reduced output slightly r beam image (1.7.5a)	educed only just
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Offside Rear jacking point rubber missing	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice make out l	Offside Headlamp deteriorated but light output not reduced out put slightly re beam image (1.7.5a)	educed only just

MOT #9	201	4-09-09 15:37
MOT test	number 4	78282154210
Result		🗸 Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	



MOT #8	2	2013-09-17 10:40
MOT test	number	305320163234
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1	.d)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #7	2012-07-14 09:33
MOT test number	777056692193
Result	✓ Passed
MOT #6	2012-07-12 13:40

MOT test number	637964392100
Result	🗙 Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #5	2011-09-14 09:29
MOT test number	716427451236
Result	✓ Passed

KS53JWL

report date: 2024-03-29





MOT #4	2010-09-27 13:33
MOT test number	320860670431
Result	✓ Passed
MOT #3	2008-12-22 13:06
MOT test number	493587758310
Result	✓ Passed
MOT #2	2007-12-14 09:22
MOT test number	800158847331
Result	✓ Passed
MOT #1	2006-12-11 12:14
MOT test number	424435346481
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 18 October 2024
Tax status	Valid until 1 June
Days left	32
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-12-29
Last registration	2023-10-10
Complete history	<u>See info</u>



Registration #1	2003-12-29	29 mi
Registration #2	2006-12-11	52.220 mi
Registration #3	2007-12-14	54.877 mi
Registration #4	2008-12-22	66.150 mi
Registration #5	2010-09-27	83.582 mi
Registration #6	2011-09-14	91.832 mi
Registration #7	2012-07-12	98.573 mi
Registration #8	2012-07-14	98.573 mi
Registration #9	2013-09-17	104.027 mi
Registration #10	2014-09-09	107.038 mi
Registration #11	2015-09-22	108.989 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.117 mi
Registration #20		11.117 mi

More info >





Dimensions & weight

Width	1980 mm
Height	1440 mm
Length	4818 mm
Wheel base	2833 mm
Kerb weight	1570 kg
Additional information	

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11291331589808