



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE PRIVILEGE VVT 136 EU4
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	191 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-11
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #21	2022-04-27 14:00
MOT test number	235320870514
Result	✓ Passed
Next expiry date	2023-05-06
Advice	Offside Rear brake dragging slightly suggest further investigation
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Nearside Front Headlamp lens slightly defective scratched and cloudy (4.1.1 (b) (i))
Advice	Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Offside Front Headlamp lens slightly defective scratched and cloudy (4.1.1 (b) (i))

MOT #20	2021-05-07 10:50
MOT test number	960358185898
Result	✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2021-04-27 14:38
MOT test number	334733574452
Result	✗ Failed
Fail	Front Headlamp aim projected beam image is obviously incorrect both side (4.1.2 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18**

2020-03-19 08:22

MOT test number

496886598784

Result

✓ Passed

Advice Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Front headlamps have slightly poor beam pattern and dim**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #17**

2019-03-27 09:39

MOT test number

250508400716

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s) both**MOT #16**

2018-03-30 11:09

MOT test number

176380859100

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front tyre worn on edges

**MOT #15** 2018-03-22 16:02**MOT test number** 994692744392**Result** ✗ Failed**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front tyre worn on edges**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)**MOT #14** 2017-03-20 17:00**MOT test number** 806612247323**Result** ✓ Passed**MOT #13** 2017-03-20 17:00**MOT test number** 582910451526**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #12** 2016-03-24 15:33**MOT test number** 712393101748**Result** ✓ Passed**Advice** Play in inner steering tie rods**Advice** Front and rear brake discs corroded

**MOT #11**

2015-03-27 10:52

MOT test number

296396585047

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10**

2015-03-25 09:50

MOT test number

717554185038

Result

✗ Failed

Fail Offside Stop lamp not working (1.2.1b)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9**

2014-02-19 12:14

MOT test number

899550454012

Result

✓ Passed

Notice Items removed from driver's view prior to test**Notice** Offside front brake disc corroded**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Nearside front brake disc corroded**Notice** Play in steering rack inner joint(s)

**MOT #8** 2014-02-19 12:14**MOT test number** 185810454057**Result** ✗ Failed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Items removed from driver's view prior to test**Notice** Offside front brake disc corroded**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Notice** Nearside front brake disc corroded**Notice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #7** 2013-01-15 10:38**MOT test number** 195945613094**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-01-15 10:38**MOT test number** 219025313075**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2012-01-23 13:03**MOT test number** 109343522034**Result** ✓ Passed

**MOT #4** 2012-01-23 10:52**MOT test number** 215753622083**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #3 2011-01-14 13:58**MOT test number** 576084511096**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brake discs corroded & pitted on inner faces
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2011-01-14 12:17**MOT test number** 459824311087**Result** ✗ Failed

- Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brake discs corroded & pitted on inner faces
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2010-01-22 11:16**MOT test number** 121042020020**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT
Date of agreement	2024-03-29
Agreement type	RENAULT
Agreement term	RENAULT
Agreement number	RENAULT
Contact info	RENAULT

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-20
Last registration	2022-04-27
Complete history	See info



Registration #1	2007-03-20	29 mi
Registration #2	2010-01-22	19.362 mi
Registration #3	2011-01-14	22.168 mi
Registration #4	2011-01-14	22.168 mi
Registration #5	2012-01-23	29.754 mi
Registration #6	2012-01-23	29.754 mi
Registration #7	2013-01-15	37.505 mi
Registration #8	2014-02-19	47.552 mi
Registration #9	2015-03-25	55.495 mi
Registration #10	2015-03-27	55.495 mi
Registration #11	2016-03-24	59.643 mi
Registration #12	2016-03-24	59.643 mi
Registration #13	2016-03-24	59.643 mi
Registration #14	2016-03-24	59.643 mi
Registration #15	2016-03-24	59.643 mi
Registration #16	2016-03-24	59.643 mi
Registration #17	2016-03-24	59.643 mi
Registration #18	2016-03-24	59.643 mi
Registration #19	2016-03-24	59.643 mi
Registration #20	2016-03-24	59.643 mi
Registration #21	2016-03-24	59.643 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Kerb weight	1410 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	C093563