





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	Black
Year of manufacture	2013
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history


Entry 1


Date 2021-08-05


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-09
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #13	2023-07-20 10:46
MOT test number	154529931197
Result	✓ Passed
Next expiry date	2024-08-09

MOT #12	2022-08-09 09:44
MOT test number	314438138807
Result	✓ Passed

MOT #11	2021-08-10 16:28
MOT test number	259191667981
Result	✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2021-08-10 16:28

MOT test number 224998377953

Result X Failed

Pass with rectification Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2020-08-03 13:46

MOT test number 906050200882

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge bald on tread edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge bald on tread edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing inner side wall (5.2.3 (d) (ii))

MOT #8 2019-04-24 12:17

MOT test number 862496739435

MOT #7 2019-04-22 15:53

MOT test number 903729561859

Result X Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also bald on edge (5.2.3 (d) (i))

Fail Offside Front Position lamp not working (4.2.1 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge bald on outer edge of tread (5.2.3 (e))

MOT #6 2018-04-26 15:29

MOT test number 573924099743

MOT #5 2018-04-24 12:26

MOT test number 226643867008

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-04-14 12:13

MOT test number 120451872518

Result X Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened inner side (3.5.1i)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #3 2017-09-14 15:51

MOT test number 328492619178

Result ✓ Passed

MOT #2 2016-10-01 09:55

MOT test number 739318291597

Result \rightarrow Passed

MOT #1 2015-10-08 10:20

MOT test number 541026671972

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner History	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-09
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-03-09	16 mi
Registration #2	2015-10-08	44.364 mi
Registration #3	2016-10-01	57.905 mi
Registration #4	2017-09-14	70.477 mi
Registration #5	2018-04-14	77.646 mi
Registration #6	2018-04-24	77.649 mi
Registration #7	2018-04-26	77.651 mi
Registration #8	2019-04-22	82.182 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles 2

Engine number D4FDDU344832