



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER
Colour	Black
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-16
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-07
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	26
Total items failed	19

MOT #20 2023-05-08 09:49

MOT test number 766728833419

Result ✓ Passed

Next expiry date 2024-05-07

Advice Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive SUSPENION AND REAR (5.3.6 (a) (i))

Advice Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive REAR AND SUMFRAME (5.3.6 (a) (i))

MOT #19 2023-05-08 09:49

MOT test number 904292851873

Result ✗ Failed

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive REAR AND SUMFRAME (5.3.6 (a) (i))

Advice Offside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive SUSPENION AND REAR (5.3.6 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #18	2022-06-16 09:39
MOT test number	152374380737
Result	✓ Passed
Advice	Unable to check headlamp levelling device

MOT #17	2022-06-15 10:15
MOT test number	126066787515
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Unable to check headlamp levelling device
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Front Headlamp aim not tested (4.1.2 (b))
Fail	Offside Rear Subframe mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))
Fail	Nearside Front Headlamp aim not tested (4.1.2 (b))
Fail	Nearside Rear Subframe mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))

**MOT #16** 2022-06-14 15:11**MOT test number** 692037903285**Result** ✗ Failed**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))**Fail** Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Fail** Offside Front Lower Seat belt anchorage prescribed area strength or continuity significantly reduced corroded area is within the same area as subframe mount corrosion (7.1.1 (a) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))**Advice** Unable to check head lamp levelling device**Fail** Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #15** 2021-05-19 10:40**MOT test number** 887252857741**Result** ✓ Passed**MOT #14** 2020-06-09 11:51**MOT test number** 330902930894**Result** ✓ Passed**MOT #13** 2019-05-24 14:06**MOT test number** 605768856346**Result** ✓ Passed**MOT #12** 2018-05-25 09:24**MOT test number** 993435719084**Result** ✓ Passed

**MOT #11** 2017-05-30 16:49**MOT test number** 806736353245**Result** ✓ Passed**MOT #10** 2017-05-27 11:04**MOT test number** 454194768321**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases backbox (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #9** 2016-05-28 09:03**MOT test number** 619366035227**Result** ✓ Passed**MOT #8** 2015-05-23 09:32**MOT test number** 356753645105**Result** ✓ Passed**Notice** N/s/f wiper smearing**Notice** O/s/f wiper smearing**MOT #7** 2014-05-24 14:23**MOT test number** 818704544111**Result** ✓ Passed**Advice** Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components

**MOT #6** 2014-05-17 15:37**MOT test number** 638447934125**Result** ✗ Failed

- Notice** Offside front tyre has a tear inner edge
- Advice** Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)
- Notice** Items removed from driver's view prior to test
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Notice** Under-trays fitted obscuring some underside components

MOT #5 2013-06-05 10:10**MOT test number** 206336653187**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)

MOT #4 2012-09-17 16:09**MOT test number** 477371162255**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-09-17 12:13**MOT test number** 456821562256**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #2 2011-09-15 15:36**MOT test number** 548298951223**Result** ✓ Passed



MOT #1	2011-09-15 12:17
MOT test number	625238851200
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage fractured (2.4.G.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	7 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YH58NMV
Plate since	2019-09-28
Current registration	YH58NMV
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-29
Last registration	2023-05-08
Complete history	See info



Registration #1	2008-09-29	6 mi
Registration #2	2011-09-15	18.239 mi
Registration #3	2011-09-15	18.239 mi
Registration #4	2012-09-17	22.049 mi
Registration #5	2012-09-17	22.055 mi
Registration #6	2013-06-05	23.377 mi
Registration #7	2014-05-17	35.205 mi
Registration #8	2014-05-24	35.375 mi
Registration #9	2015-05-23	48.277 mi
Registration #10	2016-05-28	60.358 mi
Registration #11	2017-05-27	70.700 mi
Registration #12	2018-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2020-05-29	75.377 mi
Registration #15	2021-05-29	75.377 mi
Registration #16	2022-05-29	75.377 mi
Registration #17	2023-05-08	75.377 mi
Registration #18	2023-05-08	75.377 mi
Registration #19	2023-05-08	75.377 mi
Registration #20	2023-05-08	75.377 mi
Registration #21	2023-05-08	75.377 mi
Registration #22	2023-05-08	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	L8 20260874