





report date: 2024-03-28

## General information

Make	BMW
Model	3 SERIES 320D SPORT TOURING
Colour	White
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.6 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2021-10-01

Pictures 47

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-09-24
Pictures	2
Listing price	View report





source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-23
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	9
Total items failed	9

MOT #8	2024-04-24 16:13
MOT test number	701870870215
Result	✓ Passed
Next expiry date	2025-04-23

MOT #7	2024-04-19 09:04
MOT test number	785238925463
Result	<b>X</b> Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))	
Advice Nearside Rear Nail in tyre	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm close to cords (5.2.	3 (e))
Advice Offside Front Tyre worn close to legal limit/worn on edge close to cords (5.2.3 (	(e))
Fail Offside Front Headlamp aim too high (4.1.2 (a))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge close to cords (5.2.3	3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Rear seatbelts not checked due to obstruction

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2022-10-20 10:38 **MOT** test number 147022050883 Result × Failed Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing inner edge. 4.2mm (5.2.3 (e)) Advice Rear seatbelts not checked due to obstruction Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail

MOT #4

MOT test number

Result

Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #3
 2020-12-23 10:01

 MOT test number
 908468418930

 Result
 ✓ Passed

 MOT #2
 2020-01-16 09:15

 MOT test number
 748518096853

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2020-01-13 14:38

**MOT test number** 279862491657

Result × Failed

Fail Nearside Rear Road wheel badly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
---------------	--

Owner History	
For how long did the current and previous owner(s) have this BMW? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NIX ZIX
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-11
Last registration	2024-04-24
Complete history	See info



Registration #1	2013-03-11	20 mi
Registration #2	2020-01-13	34.815 mi
Registration #3	2020-01-16	34.815 mi
Registration #4	2020-12-23	40.545 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		71.777 66
Registration #11		0.00 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
0482	
0501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



## Dimensions & weight

Width	1811 mm
Height	1462 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1500 kg
Max. allowed weight	2050 kg

# Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 82808376