



RENAULT

VU56YMH

report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LH 35 DCI 120 P/V
Colour	White
Year of manufacture	2006
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Engine capacity	2.463 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-18
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	53
Total items failed	12

MOT #23	2024-04-11 08:56
MOT test number	920611077418
Result	✓ Passed
Next expiry date	2025-04-18

MOT #22	2023-04-19 09:37
MOT test number	344902657990
Result	✓ Passed

MOT #21	2023-04-19 09:37
MOT test number	305609073801
Result	✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #20	2022-03-29 13:04
MOT test number	283427006002
Result	✓ Passed

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #19**

2022-03-29 13:04

MOT test number

654894931827

Result

✗ Failed

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2021-04-14 10:05

MOT test number

274918235432

Result

✓ Passed

MOT #17

2019-07-08 07:32

MOT test number

955770215423

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16

2019-07-08 07:32

MOT test number

207100928229

Result

✗ Failed

Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2018-07-11 13:28**MOT test number** 641842219319**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2018-07-11 08:23**MOT test number** 425869490357**Result** ✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Brake cable damaged (1.1.15 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2017-07-06 08:51**MOT test number** 122272901204**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Drag link end ball joint has slight play drumstick (2.2.B.1f)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2016-07-18 09:52**MOT test number** 534697322638**Result** ✓ Passed**Advice** Nearside Drag link end ball joint has slight play drumstick (2.2.B.1f)**MOT #11** 2016-07-11 07:22**MOT test number** 885817362158**Result** ✗ Failed**Fail** Offside Steering rack gaiter split (2.2.D.2d)**Advice** Nearside Drag link end ball joint has slight play drumstick (2.2.B.1f)**Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)**MOT #10** 2015-07-08 12:28**MOT test number** 535009585112**Result** ✓ Passed**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Notice** Nail in nearside front tyre**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #9**

2015-07-07 08:33

MOT test number

908858885157

Result**✗ Failed****Fail**

Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice

Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Notice

Nail in nearside front tyre

Advice

Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #8

2014-07-17 08:46

MOT test number

499578994154

Result**✓ Passed****Advice**

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7

2013-06-22 08:55

MOT test number

159363873171

Result**✓ Passed****Advice**

Offside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #6** 2012-06-19 16:48**MOT test number** 996781572147**Result** ✓ Passed

- Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-06-19 16:48**MOT test number** 698841972141**Result** ✗ Failed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Pass with rectification** Registration plate lamp not working (1.1.C.1d)

MOT #4 2011-04-04 12:56**MOT test number** 845024991088**Result** ✓ Passed

**MOT #3** 2011-04-02 11:02**MOT test number** 716382391020**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front front brake binding (3.7.B.1)**MOT #2** 2009-10-13 12:21**MOT test number** 700886389287**Result** ✓ Passed**MOT #1** 2009-10-13 09:19**MOT test number** 183486989286**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Rear Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
18 April 2025

Tax status		Valid until 1 May
Days left		1
MOT expiry date		18 April 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-10-16
Last registration	2024-04-11
Complete history	See info



Registration #1	2006-10-16	8 mi
Registration #2	2009-10-13	116.055 mi
Registration #3	2009-10-13	116.055 mi
Registration #4	2011-04-02	120.121 mi
Registration #5	2011-04-04	120.122 mi
Registration #6	2012-06-19	123.194 mi
Registration #7	2013-06-22	125.052 mi
Registration #8	2014-07-17	127.110 mi
Registration #9	2015-07-07	129.084 mi
Registration #10	2015-07-08	129.084 mi
Registration #11	2016-07-11	131.334 mi
Registration #12	2016-07-18	131.334 mi
Registration #13	2016-07-18	131.334 mi
Registration #14	2016-07-18	131.334 mi
Registration #15	2016-07-18	131.334 mi
Registration #16	2016-07-18	131.334 mi
Registration #17	2016-07-18	131.334 mi
Registration #18	2016-07-18	131.334 mi
Registration #19	2016-07-18	131.334 mi
Registration #20	2016-07-18	131.334 mi
Registration #21	2016-07-18	131.334 mi
Registration #22	2016-07-18	131.334 mi
Registration #23	2016-07-18	131.334 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1990 mm
Height	2200 mm
Length	6330 mm
Wheel base	4078 mm
Kerb weight	1949 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	C026223