





General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | TIGUAN SE TDI |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 127 mph |
| 0 - 100 km/h | 9.3 seconds |
| 0 - 60 mph | 9.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 148 BHP |
|-------------------------|---------------------------|
| Max. torque | 340 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 126 g/km |
| CO2 label | D |





| Internet history | |
|------------------------|-------------|
| Entry 2 | |
| Date | 2022-01-18 |
| Pictures | 0 |
| Listing price | View report |
| source: cargurus.co.uk | |
| Entry 1 | |
| Date | 2022-01-16 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-05-10 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 0 |

| МОТ #4 | 2023-05-11 09:47 |
|--|------------------|
| MOT test number | 900813851218 |
| Result | ✓ Passed |
| Next expiry date 2024-05-1 | |
| MinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))AdviceOffside Rear Nail in tyre | |

| MOT #3 | 2022-05-06 07:10 |
|-----------------|------------------|
| MOT test number | 190207872943 |
| Result | ✓ Passed |
| | |

| MOT #2 | 2021-08-13 08:55 |
|-----------------|------------------|
| MOT test number | 589369445021 |
| Result | ✓ Passed |





| MOT #1 | 2021-08-10 13:54 |
|----------|--|
| MOT test | number 59786829843 |
| Result | × Failed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| DANGER | OUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |



Tax & MOT check

| √ Taxed | √ MOT |
|------------------------|--------------------------------|
| Tax due: 1 May 2025 | Expires: 10 May 2024 |
| Tax status | Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 10 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEED ON |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE I |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******** | |
| | |
| and the second sec | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow



SD68PSO report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-10-30 |
| Last registration | 2023-05-11 |
| Complete history | See info |



| Registration #1 | 2018-10-30 | 14 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-08-10 | 32.927 mi |
| Registration #3 | 2021-08-13 | 32.927 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 96% |
| Children | 84% |
| Pedestrian | 72% |
| Safety systems | 68% |
| Overall rating | 83% |
| Video | <u>see crash video</u> |



| Dimensions & weight | | |
|------------------------|------------------|------------|
| Width | 2099 mm | |
| Height | 1632 mm | |
| Length | 4486 mm | |
| Wheel base | 2677 mm | |
| Kerb weight | 1568 kg | |
| Max. allowed weight | 2170 kg | |
| Additional information | | |
| Fuel tank capacity | 58 I | |
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| CarCheck.co.uk | | page 11/11 |

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DFGA877015 |