



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-08-10
Pictures	14
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-09-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	28
Total items failed	1

MOT #15 2023-09-25 11:56**MOT test number** 247019688728**Result** Passed**Next expiry date** 2024-09-24

- Advice** Exhaust has a minor leak of exhaust gases middle (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2022-09-13 10:58**MOT test number** 739955338824**Result** Passed

- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2021-08-23 16:31**MOT test number** 680755015654**Result** ✓ Passed**MOT #12** 2021-08-23 14:08**MOT test number** 944979054160**Result** ✗ Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11 2020-09-18 15:56**MOT test number** 478548083320**Result** ✓ Passed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face highly corroded and strongly advise replacing. (1.1.14 (a) (ii))

Minor Offside Front Tyre obviously under inflated (5.2.3 (l))

Advice Offside Front Nail in tyre

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face highly corroded and strongly advise replacing. (1.1.14 (a) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated weeping grease and perishing. (6.1.7 (g) (i))

**MOT #10** 2020-09-18 11:37**MOT test number** 265085831530**Result** ✗ Failed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face highly corroded and strongly advise replacing. (1.1.14 (a) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Offside Front Tyre obviously under inflated (5.2.3 (l))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face highly corroded and strongly advise replacing. (1.1.14 (a) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated weeping grease and perishing. (6.1.7 (g) (i))

Advice Offside Front Nail in tyre

MOT #9 2019-05-08 11:05**MOT test number** 759542082219**Result** ✓ Passed**MOT #8** 2018-05-14 09:18**MOT test number** 884045230260**Result** ✓ Passed**MOT #7** 2017-05-12 13:44**MOT test number** 196253963000**Result** ✓ Passed**MOT #6** 2016-05-13 09:16**MOT test number** 669064343603**Result** ✓ Passed

**MOT #5** 2015-01-13 11:40**MOT test number** 238753915009**Result** ✓ Passed**MOT #4** 2014-05-22 11:15**MOT test number** 618322544100**Result** ✓ Passed**Notice** Front tyres wearing on outside**MOT #3** 2013-05-30 12:45**MOT test number** 529690053117**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-05-23 09:56**MOT test number** 478713343150**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #1** 2011-06-28 16:56**MOT test number** 827709671166**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 September 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DV58LWU
Plate since	2019-03-29
Current registration	 DV58LWU
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-25
Last registration	2023-09-25
Complete history	See info



Registration #1	2008-11-25	14 mi
Registration #2	2011-06-28	25.586 mi
Registration #3	2013-05-23	53.014 mi
Registration #4	2013-05-30	53.017 mi
Registration #5	2014-05-22	66.988 mi
Registration #6	2015-01-13	76.150 mi
Registration #7	2016-05-13	93.476 mi
Registration #8	2017-05-12	103.848 mi
Registration #9	2018-05-14	113.841 mi
Registration #10	2019-05-20	123.834 mi
Registration #11	2020-05-20	133.827 mi
Registration #12	2021-05-20	143.820 mi
Registration #13	2022-05-20	153.813 mi
Registration #14	2023-05-20	163.806 mi
Registration #15	2024-05-20	173.799 mi
Registration #16	2025-05-20	183.792 mi
Registration #17	2026-05-20	193.785 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163