



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SPORT
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D









Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2022-02-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	5
Total items failed	7

MOT #15	2021-02-08 13:53
MOT test number	874895673067
Result	✓ Passed
Next expiry date	2022-02-07
Advice	Nearside Front fog glass broken.

MOT #14	2021-02-06 07:10
MOT test number	324115853211
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front fog glass broken.
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #13	2019-06-07 16:33
MOT test number	995066772283
Result	✓ Passed

**MOT #12** 2019-06-07 15:59**MOT test number** 365847941863**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2018-06-29 13:40**MOT test number** 568216407375**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front and n/s/r (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2017-07-03 11:07**MOT test number** 262818845545**Result** ✓ Passed**MOT #9** 2017-07-03 09:03**MOT test number** 719093122709**Result** ✗ Failed**Fail** Nearside Side repeater missing (1.4.A.2b)**MOT #8** 2016-06-21 13:25**MOT test number** 400381199205**Result** ✓ Passed**MOT #7** 2016-06-21 08:04**MOT test number** 161859972941**Result** ✗ Failed**Fail** Headlamp not working on dipped beam BOTH SIDES (1.7.5a)

**MOT #6** 2015-06-30 09:10**MOT test number** 695181685120**Result** ✓ Passed**MOT #5** 2014-07-02 17:05**MOT test number** 767653684101**Result** ✓ Passed**MOT #4** 2014-07-02 09:15**MOT test number** 347533384103**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #3** 2013-06-12 11:30**MOT test number** 915823663148**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-06-08 09:20**MOT test number** 609900462138**Result** ✓ Passed**MOT #1** 2011-06-29 11:19**MOT test number** 725880181138**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-04
Last registration	2021-02-08
Complete history	See info



Registration #1	2008-07-04	28 mi
Registration #2	2011-06-29	44.064 mi
Registration #3	2012-06-08	54.102 mi
Registration #4	2013-06-12	65.587 mi
Registration #5	2014-07-02	74.859 mi
Registration #6	2014-07-02	74.862 mi
Registration #7	2015-06-30	82.259 mi
Registration #8	2016-06-21	88.724 mi
Registration #9	2016-06-21	88.727 mi
Registration #10	2016-06-21	88.727 mi
Registration #11	2016-06-21	88.727 mi
Registration #12	2016-06-21	88.727 mi
Registration #13	2016-06-21	88.727 mi
Registration #14	2016-06-21	88.727 mi
Registration #15	2016-06-21	88.727 mi
Registration #16	2016-06-21	88.727 mi
Registration #17	2016-06-21	88.727 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

473928