





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SPORT
Colour	Blue
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	35.3 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-04-03
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	28
Total items failed	8

MOT #22	2024-04-04 10:35
MOT test number	833633015994
Result	✓ Passed
Next expiry date	2025-04-03
Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	

MOT #21	2024-04-03 14:21
MOT test number	796197018891
Result	× Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #20		2022-11-07 09:46
MOT test	number	850389585553
Result		✓ Passed
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (FRONT) (5.3.4 (a) (i))		
Advice	Offside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/14



Advice

Advice

PJ06WHH

report date: 2024-03-28

MOT test number

679248992138

Result

Fail Offside Front Suspension arm pin or bush excessively worn (FRONT) (5.3.4 (a) (i))

Advice Offside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (FRONT) (5.3.4 (a) (i))

Nearside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #18

MOT test number

299698571516

Result

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17		2020-10-28 09:08
MOT test	number	565416408526
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-28

Passed

MOT #16 2019-06-04 08:47

MOT test number 433420628635

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on both edges (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on both edges and perished (strong

advise) (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge worn on edge and perished (5.2.3

(e))

Result

MOT #15 2018-06-11 11:20

MOT test number 554081126675

Result ✓ Passed

MOT #14 2017-08-18 12:54

MOT test number 947234125991

Result \(\sqrt{Passed} \)

MOT #13 2016-08-16 08:19

MOT test number 108858186665

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2015-08-21 15:16

MOT test number 220329616564

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #11

MOT test number

788387025224

Result

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #10

MOT test number

617986114261

Result

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

Notice Front tyres wearing on inner edges

MOT #9

MOT test number

298305853177

Result

Notice No print out was produced due to low emissions.

MOT test number

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Notice No print out was produced due to low emissions.

MOT #7

MOT test number

859266862114

Result

✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice | Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #5
 2011-06-11 12:02

 MOT test number
 519152261185

 Result
 ✓ Passed

 MOT #4
 2010-06-02 16:57

 MOT test number
 891803050147

 Result
 ✓ Passed

 Notice
 Nail in offside rear tyre

MOT #3

MOT test number

Result

Pass with rectification Offside Fuel tank leaking (7.2.3)

Notice Nail in offside rear tyre

 MOT #2
 2009-06-29 10:33

 MOT test number
 220020089465

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

MOT #1

MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full research	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	UK UK

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-02
Last registration	2024-04-04
Complete history	See info



Registration #1	2006-06-02	6 mi
Registration #2	2009-06-29	20.797 mi
Registration #3	2010-06-02	26.844 mi
Registration #4	2011-06-11	34.169 mi
Registration #5	2012-06-12	42.282 mi
Registration #6	2012-06-14	42.282 mi
Registration #7	2013-05-31	49.464 mi
Registration #8	2013-06-04	49.464 mi
Registration #9	2014-08-04	55.494 mi
Registration #10	2015-08-15	58.341 mi
Registration #11	2015-08-21	58.348 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	01265727G

CarCheck.co.uk page 14/14