



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA CRDI GS
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	16.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-11
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #15	2024-01-16 10:04
MOT test number	201597284220
Result	✓ Passed
Next expiry date	2025-01-24
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-01-20 09:40
MOT test number	434664022861
Result	✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13	2022-01-07 10:14
MOT test number	365342703982
Result	✓ Passed

**MOT #12** 2022-01-04 10:41**MOT test number** 299327541501**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #11** 2021-01-11 15:02**MOT test number** 338061313338**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2019-07-25 13:09**MOT test number** 285524600745**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-07-25 10:04**MOT test number** 767611035684**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #8** 2018-05-02 10:15**MOT test number** 539227033420**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit 2.8mm (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2017-05-11 10:01**MOT test number** 857277587262**Result** ✓ Passed**MOT #6** 2016-06-30 11:30**MOT test number** 728817798803**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-06-24 15:25**MOT test number** 776335475131**Result** ✓ Passed**MOT #4** 2015-06-24 12:35**MOT test number** 808795875117**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2014-07-02 13:03
MOT test number	387063184134
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	N/s/r tyre worn outer shoulder

MOT #2	2013-07-22 16:48
MOT test number	778713503205
Result	✓ Passed
Notice	Rear tyres wearing slightly on edge

MOT #1	2012-08-03 12:15
MOT test number	656186712224
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-03
Last registration	2024-01-16
Complete history	See info



Registration #1	2009-09-03	15 mi
Registration #2	2012-08-03	17.184 mi
Registration #3	2013-07-22	22.562 mi
Registration #4	2014-07-02	27.048 mi
Registration #5	2015-06-24	31.655 mi
Registration #6	2015-06-24	31.655 mi
Registration #7	2016-06-30	35.714 mi
Registration #8	2017-05-11	39.783 mi
Registration #9	2018-05-02	51.734 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2189 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3827710