



report date: 2024-03-29

General information

Make	NISSAN
Model	CUBE KAIZEN
Colour	Black
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	151 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-21
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-20
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	27
Total items failed	17

MOT #17	2024-02-12 16:32
MOT test number	219311496417
Result	✓ Passed
Next expiry date	2025-02-20
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened boh (1.1.14 (a) (ii))

MOT #16	2024-02-12 09:17
MOT test number	456743259539
Result	✗ Failed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened boh (1.1.14 (a) (ii))
Fail	Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Rear Outer Seat belt buckle damaged (7.1.2 (d))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #15	2023-02-16 10:11
MOT test number	804593957758
Result	✓ Passed
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2023-02-16 10:11

MOT test number

800439301202

Result

✗ Failed

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2022-02-21 15:57

MOT test number

118826707239

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2021-02-01 15:00

MOT test number

995772141441

Result

✓ Passed

Advice Nearside Tyre slightly damaged/cracking or perishing both nearside tyre sidewalls perishing (5.2.3 (d) (ii))**Advice** Rear Brake hose has slight corrosion to ferrule both rear brake hoses ferrules corroded (1.1.12 (f) (i))

**MOT #11** 2021-02-01 10:23**MOT test number** 691545294111**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Tyre slightly damaged/cracking or perishing both nearside tyre sidewalls perishing (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake hose has slight corrosion to ferrule both rear brake hoses ferrules corroded (1.1.12 (f) (i))**MOT #10** 2020-02-14 13:56**MOT test number** 699877428244**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2019-02-11 09:53**MOT test number** 609184340618**Result** ✓ Passed**MOT #8** 2018-02-09 10:45**MOT test number** 181477416096**Result** ✓ Passed**MOT #7** 2017-01-26 21:40**MOT test number** 267944358051**Result** ✓ Passed**Advice** Central stop lamp not working

**MOT #6** 2017-01-26 09:55**MOT test number** 642544208993**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Central stop lamp not working**MOT #5** 2015-11-26 10:23**MOT test number** 840083823525**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Off side mirror is secured with tape**MOT #4** 2015-11-25 11:54**MOT test number** 184446260434**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Off side mirror is secured with tape**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Headlamp aim too low (1.8)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**MOT #3** 2014-11-25 11:59**MOT test number** 618479824324**Result** ✓ Passed



MOT #2	2013-11-21 11:32
MOT test number	858145223323
Result	✓ Passed
Notice	Off side mirror is secured with tape
Notice	NAIL IN THE NEAR SIDE REAR TYRE

MOT #1	2013-11-15 11:59
MOT test number	648469913352
Result	✗ Failed
Fail	Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Off side mirror is secured with tape
Fail	Electronic stability system warning lamp indicates a fault (3.4.1c)
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Notice	NAIL IN THE NEAR SIDE REAR TYRE
Fail	Brake fluid warning lamp illuminated (3.6.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
20 February 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	20 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-27
Last registration	2024-02-12
Complete history	See info



Registration #1	2010-09-27	26 mi
Registration #2	2013-11-15	36.091 mi
Registration #3	2013-11-21	36.098 mi
Registration #4	2014-11-25	46.380 mi
Registration #5	2015-11-25	53.566 mi
Registration #6	2015-11-26	53.566 mi
Registration #7	2017-01-26	56.102 mi
Registration #8	2017-01-26	56.102 mi
Registration #9	2018-02-09	57.789 mi
Registration #10	2019-02-11	58.691 mi
Registration #11	2019-05-20	59.377 mi
Registration #12	2019-05-20	59.377 mi
Registration #13	2019-05-20	59.377 mi
Registration #14	2019-05-20	59.377 mi
Registration #15	2019-05-20	59.377 mi
Registration #16	2019-05-20	59.377 mi
Registration #17	2019-05-20	59.377 mi
Registration #18	2019-05-20	59.377 mi
Registration #19	2019-05-20	59.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	64%
Pedestrian	56%
Safety systems	84%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1680 mm
Length	3980 mm
Wheel base	2530 mm
Kerb weight	1230 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	245005