



report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Black
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	158 g/km
CO2 label	G





MOT history

MOT expiry date	2021-01-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	42
Total items failed	2

MOT #15	2020-01-07 12:13
MOT test number	242847550890
Result	✓ Passed
Next expiry date	2021-01-24
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Exhaust heat shield insecure
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #14**

2020-01-03 11:29

MOT test number

567117414446

Result**✗ Failed****DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13**

2019-01-25 13:51

MOT test number

524575766236

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #12**

2018-08-09 16:29

MOT test number

403858305204

Result**✓ Passed****Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #11**

2018-07-25 14:18

MOT test number

495964094521

Result**✗ Failed**

- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn axle (5.3.4 (a) (i))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Brake fluid contaminated (1.8 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Brake pedal anti-slip provision worn smooth (1.1.2 (c))
- MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn axle (5.3.4 (a) (i))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- MAJOR** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #10

2017-05-19 10:45

MOT test number

649053746248

Result**✓ Passed**

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-11-18 12:10**MOT test number** 224684874177**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2014-11-26 16:20**MOT test number** 985240334345**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2013-11-13 13:37**MOT test number** 379347713352**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-11-13 09:46**MOT test number** 566647313382**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)



MOT #5	2012-11-08 09:50
MOT test number	228013512350
Result	✓ Passed
MOT #4	2011-11-24 15:06
MOT test number	169168021363
Result	✓ Passed
MOT #3	2010-11-24 15:40
MOT test number	494468920329
Result	✓ Passed
MOT #2	2009-11-24 10:36
MOT test number	301498129366
Result	✓ Passed
MOT #1	2008-11-26 08:09
MOT test number	943651538354
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
15 January 2021

X

MOT

Expired:
24 January 2021

Tax status	Expired at 15 January 2021
Days left	1200 days too late
MOT expiry date	24 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2005-11-29
Last registration	2020-01-07
Complete history	See info



Registration #1	2005-11-29	20 mi
Registration #2	2008-11-26	26.579 mi
Registration #3	2009-11-24	34.143 mi
Registration #4	2010-11-24	42.189 mi
Registration #5	2011-11-24	49.811 mi
Registration #6	2012-11-08	56.288 mi
Registration #7	2013-11-13	65.764 mi
Registration #8	2013-11-13	65.764 mi
Registration #9	2014-11-13	75.240 mi
Registration #10	2015-11-13	84.716 mi
Registration #11	2016-11-13	94.192 mi
Registration #12	2017-11-13	103.668 mi
Registration #13	2018-11-13	113.144 mi
Registration #14	2019-11-13	122.620 mi
Registration #15	2020-01-07	132.096 mi
Registration #16	2020-01-07	141.572 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1088 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	4T67886
---------------	---------