





report date: 2024-03-28

General information

Make	FORD
Model	KA TITANIUM
Colour	Red
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-10

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2024-11-03
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	10

MOT #10	2023-10-25 09:21
MOT test number	835417417437
Result	✓ Passed
Next expiry date	2024-11-03
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #9	2022-11-04 11:52
MOT test number	849168638728
Result	✓ Passed

MOT #8	2021-11-04 13:41
MOT test number	580536314221
Result	✓ Passed

MOT #7	2021-02-04 17:05

MOT test number 787399520387

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #6 2021-02-01 13:28

MOT test number 402620406909

Result X Failed

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Oil leaking excessively from engine sump (8.4.1 (a) (i))

MOT #5 2020-01-30 16:27

MOT test number 162202613461

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

CarCheck.co.uk page 4/12



MOT #4 2020-01-30 12:50

MOT test number 262873880655

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3 2019-02-02 13:33

MOT test number 926327359503

Result
✓ Passed

Advice Unable to check rear seatbelts

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #2 2019-02-02 11:45

MOT test number 545474672347

Result X Failed

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Unable to check rear seatbelts

MOT #1 2018-02-02 13:37

MOT test number 342042658464

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-01-31
Last registration	2023-10-25
Complete history	See info



2015-01-31	16 mi
2018-02-02	26.847 mi
2019-02-02	37.383 mi
2019-02-02	37.383 mi
2020-01-30	47.231 mi
2020-01-30	47.231 mi
	91,777 esi
	11.777 es
	91.777 esi
	11.777 es
	11.777 es
	2018-02-02 2019-02-02 2019-02-02 2020-01-30

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 I
Number of axles	2
Engine number	1361424

CarCheck.co.uk page 12/12