



report date: 2024-03-28

General information

Make	FIAT
Model	500 C POP
Colour	White
Year of manufacture	2009
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-02-11
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	40
Total items failed	6

MOT #14	2024-01-08 16:20
MOT test number	992001549126
Result	✓ Passed
Next expiry date	2025-01-07

MOT #13	2023-01-03 13:48
MOT test number	386436569563
Result	✓ Passed

MOT #12	2021-09-25 11:39
MOT test number	354440789721
Result	✓ Passed
Advice	Rear axle corroded
Advice	Exhaust corroded



MOT #11

2020-10-03 10:59

MOT test number

863771055578

Result

✓ Passed

- Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Exhaust corroded
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Exhaust flexible joint deteriorated
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2020-09-30 15:43

MOT test number

842649374456

Result**✗ Failed****Advice**

Exhaust corroded

DANGEROUS

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Rear Brake cable damaged (1.1.15 (a))

Advice

Exhaust flexible joint deteriorated

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2019-04-05 15:08

MOT test number

560468725823

Result**✓ Passed****MOT #8**

2018-04-06 07:49

MOT test number

864494469925

Result**✓ Passed****Advice**

Nearside Front Nail in tyre 2

Advice

Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2018-04-03 11:15

MOT test number

946259076505

Result**✗ Failed**

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear handbrake outer casing split and swollen not affecting operation
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Air intake pipe insecure
- Advice** Oil leak slight leak from gear selector oil seal
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust back box outer skin peeling
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear handbrake cable outer casing split and swollen not affecting operation
- Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)

MOT #6

2017-03-14 15:29

MOT test number

831293088271

Result**✓ Passed**

- Advice** Corrosion to exhaust.back box outer skin loose.
- Advice** Brake disc worn, pitted or scored, but not seriously weakened fronts. (3.5.1i)

**MOT #5** 2017-03-14 13:01**MOT test number** 126996899030**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened fronts. (3.5.1i)**Fail** Nearside Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' obsolete tax disc holder. (8.3.1e)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Corrosion to exhaust.back box outer skin loose.**Fail** Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2016-03-01 14:35**MOT test number** 938201398335**Result** ✓ Passed**Advice** General corrosion to exhaust.**MOT #3** 2015-02-24 12:53**MOT test number** 159185555442**Result** ✓ Passed**Notice** EXHAUST CORRODED**MOT #2** 2014-03-14 13:30**MOT test number** 637173074004**Result** ✓ Passed**MOT #1** 2012-07-12 14:37**MOT test number** 765364392160**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
7 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-08-06
Last registration	2024-01-08
Complete history	See info



Registration #1	2009-08-06	28 mi
Registration #2	2012-07-12	14.945 mi
Registration #3	2014-03-14	21.681 mi
Registration #4	2015-02-24	23.906 mi
Registration #5	2016-03-01	26.381 mi
Registration #6	2017-03-14	28.180 mi
Registration #7	2017-03-14	28.180 mi
Registration #8	2018-04-03	32.875 mi
Registration #9	2019-05-20	35.277 mi
Registration #10	2020-05-20	35.277 mi
Registration #11	2021-05-20	35.277 mi
Registration #12	2022-05-20	35.277 mi
Registration #13	2023-05-20	35.277 mi
Registration #14	2024-01-08	35.277 mi
Registration #15	2024-01-08	35.277 mi
Registration #16	2024-01-08	35.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5331536