





General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | FOX URBAN FOX |
| Colour | Beige |
| Year of manufacture | 2010 |
| Top speed | 92 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 55 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------------------------------|
| Max. torque | 108 Nm at 3.000 rpm | 101 - 120 ^B _C |
| Engine capacity | 1.198 cc | 121 - 140 E |
| Cylinders | 3 | 141 - 165 F |
| Fuel type | Petrol | 166 - 185 H |
| Consumption city | 36.2 mpg | 186 - 225 J |
| Consumption extra urban | 55.4 mpg | 225+ |
| Consumption combined | 46.3 mpg | |
| CO2 emission | 139 g/km | |
| CO2 label | E | |
| | | |





Internet history

| Entry | 1 |
|-------|---|
| | |

Date Pictures 2021-07-02

12

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-14 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 12 |
| Failed MOT tests | 4 |
| Total advice items | 21 |
| Total items failed | 8 |

| MOT #16 | | 2023-07-11 14:50 |
|---------------|--|------------------------|
| MOT test | number | 674413360017 |
| Result | | ✓ Passed |
| Next exp | iry date | 2024-07-14 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge On legal limit (5.2 | 2.3 (e)) |
| Advice | Nearside & Offside rear shock absorber covers broken | |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or lig | ght sources (4.7.1 (b) |

| MOT #15 | 2023-07-11 09:41 |
|--|-----------------------------|
| MOT test number | 870743809534 |
| Result | 🗙 Failed |
| Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge On legal limit | t (5.2.3 (e)) |
| Advice Nearside & Offside rear shock absorber covers broken | |
| (i)) Offside Registration plate lamp inoperative in the case of multiple lamps | or light sources (4.7.1 (b) |





| MOT #14 | 2022-07-3 | 13 09:34 |
|-----------------------------------|--|----------|
| MOT test number | 516290 | 6039359 |
| Result | | Passed |
| Advice Nearside etc | Front Lower suspension arm ball joint dust cover split, but preventing the ingress | of dirt |
| Advice Engine m | ount(s) worn | |
| | | |
| MOT #13 | 2022-07-3 | 13 09:34 |
| MOT test number | 596344 | 4518759 |
| Result | | 🗙 Failed |
| Pass with rectific | | |
| Advice Engine m | ount(s) worn | |
| Pass with rectific (4.1.2 (c)) | Nearside Headlamp aim projected beam image is obviously incorrect lens | s foggy |
| Advice Nearside | Front Lower suspension arm ball joint dust cover split, but preventing the ingress | of dirt |

| MOT #12 | 2021-07-15 10:40 |
|-----------------|------------------|
| MOT test number | 122504504269 |
| Result | ✓ Passed |





| MOT #11 | 2021-07-13 12:38 |
|--|------------------|
| MOT test number | 841989145090 |
| Result | 🗙 Failed |
| Advice Front and rear tyres different sizes | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Exhaust has a minor leak of exhaust gases rear silencer holed (6.1.2 (a)) | |
| Fail Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| MOT #10 | 2020-09-17 13:51 |
|---|------------------|
| MOT test number | 662369086020 |
| Result | ✓ Passed |
| Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e)) | |

| МОТ #9 | 2020-09-17 09:08 |
|--|------------------|
| MOT test number | 896122229036 |
| Result | 🗙 Failed |
| Fail Suspension arm pin or bush excessively worn rear of n/s and o/s front inners (5 | 5.3.4 (a) (i)) |
| Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e)) | |
| Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) | |





| MOT #8 | 2019-09-19 08:41 |
|---|---------------------|
| MOT test number | 354170179737 |
| Result | ✓ Passed |
| AdviceSuspension arm pin or bush worn but not resulting in excessive movement front inners (5.3.4 (a) (i))Advice185 tyres fitted to front and 175 fitted to rear | rear of n/s and o/s |
| MOT #7 | 2018-09-14 09:12 |
| MOT test number | 329811011703 |
| Result | ✓ Passed |
| Advice Suspension arm pin or bush worn but not resulting in excessive movement rear of n/s and o/s front inners (5.3.4 (a) (i)) | |

| MOT #C | 2017 00 21 00.16 |
|---|------------------|
| MOT #6 | 2017-09-21 09:16 |
| MOT test number | 453643566022 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| | |
| MOT #5 | 2016-09-15 07:55 |
| MOT test number | 104318131729 |
| Result | ✓ Passed |
| | |
| МОТ #4 | 2015-09-16 07:49 |
| MOT test number | 827031449989 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2014-09-23 08:24 |
| MOT test number | 827336264205 |
| | |

Result

🗸 Passed





| MOT #2 | 2014-01-29 10:48 |
|-----------------|------------------|
| MOT test number | 557949324002 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2013-01-30 15:48 |
| MOT test number | 108800033485 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 January 2025 | ✓ MOT Expires: 14 July 2024 |
|--|--------------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 14 July 2024 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FETT |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE . |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******** | |
| | |
| and a second sec | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2010-06-21 |
| Last registration | 2023-07-11 |
| Complete history | See info |



| Registration #1 | 2010-06-21 | 11 mi |
|------------------|------------|-------------|
| Registration #2 | 2013-01-30 | 17.122 mi |
| Registration #3 | 2014-01-29 | 20.431 mi |
| Registration #4 | 2014-09-23 | 23.931 mi |
| Registration #5 | 2015-09-16 | 35.417 mi |
| Registration #6 | 2016-09-15 | 43.136 mi |
| Registration #7 | 2017-09-21 | 48.792 mi |
| Registration #8 | 2018-09-14 | 54.684 mi |
| Registration #9 | 2019-09-19 | 59.657 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 est |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 esi |
| Registration #18 | | 10. 100 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information **Fuel tank capacity** 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

| Number of seats | 4 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CHF 068554 |