



HJ030WM

report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Beige
Year of manufacture	2003
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	135 Nm at 3.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-07-13
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-26
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	38
Total items failed	6

MOT #23	2023-03-27 10:39
MOT test number	834125452682
Result	✓ Passed
Next expiry date	2024-03-26
Advice	Central Rear Exhaust has a minor leak of exhaust gases pipe to box joint/corroded (6.1.2 (a))

MOT #22	2023-02-28 13:19
MOT test number	313767706204
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Stop lamp(s) all not working (4.3.1 (a) (iii))
MAJOR	Offside Rear Brake pipe excessively corroded TO flexi (1.1.11 (c))
MAJOR	Front Exhaust has a major leak of exhaust gases down pipe joint (6.1.2 (a))
Minor	Power steering fluid level below minimum (2.1.5 (b) (i))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear wiper & washer inoperative
MAJOR	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
MAJOR	Hydraulic fluid leaking excessively power steer pipes ? (8.4.1 (a) (i))

**MOT #21**

2022-02-09 13:55

MOT test number

459431094814

Result

✓ Passed

- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge. (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #20

2022-02-04 15:31

MOT test number

480741220781

Result

✗ Failed

- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge. (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19

2021-01-29 14:31

MOT test number

213586203488

Result

✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))



MOT #18	2020-01-25 09:39
MOT test number	335030361671
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #17	2019-02-07 17:21
MOT test number	633502194469
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2019-02-06 16:00
MOT test number	524590461419
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2018-02-08 16:44
MOT test number	623771660970
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases blow at joint between front pipe and centre pipe. (7.1.2)

MOT #14	2018-02-07 16:47
MOT test number	750209069082
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases blow at joint between front pipe and centre pipe. (7.1.2)
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits 1.06 (7.3.D.3)
Fail	Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #13** 2017-02-16 15:59**MOT test number** 178386872039**Result** ✓ Passed**MOT #12** 2017-02-10 18:02**MOT test number** 135703720905**Result** ✗ Failed**Advice** Offside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Outer Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #11** 2016-03-05 08:50**MOT test number** 294342108973**Result** ✓ Passed**MOT #10** 2015-03-07 08:19**MOT test number** 247816565051**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2014-03-08 08:38**MOT test number** 497097864017**Result** ✓ Passed

**MOT #8** 2013-03-09 08:48**MOT test number** 189618163483**Result** ✓ Passed**MOT #7** 2012-03-03 08:37**MOT test number** 648323462039**Result** ✓ Passed**MOT #6** 2011-03-05 11:48**MOT test number** 625024861053**Result** ✓ Passed**Notice** New tyres fitted on rear**MOT #5** 2010-03-06 09:10**MOT test number** 624335060050**Result** ✓ Passed**Notice** X2 rear tyres have slight cracking on side walls**MOT #4** 2009-02-26 09:03**MOT test number** 294747959068**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-02-23 10:13**MOT test number** 503454958098**Result** ✓ Passed



MOT #2	2007-02-08 12:31
MOT test number	610689737034
Result	✓ Passed
MOT #1	2006-02-02 12:24
MOT test number	852113436038
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
26 March 2024

Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	26 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-04-19
Last registration	2023-03-27
Complete history	See info



Registration #1	2003-04-19	19 mi
Registration #2	2006-02-02	13.839 mi
Registration #3	2007-02-08	19.008 mi
Registration #4	2008-02-23	25.789 mi
Registration #5	2009-02-26	32.663 mi
Registration #6	2010-03-06	40.318 mi
Registration #7	2011-03-05	45.983 mi
Registration #8	2012-03-03	51.416 mi
Registration #9	2013-03-09	58.244 mi
Registration #10	2014-03-08	65.089 mi
Registration #11	2015-03-07	72.530 mi
Registration #12	2016-03-05	82.164 mi
Registration #13	2017-02-10	89.029 mi
Registration #14	2018-03-09	95.377 mi
Registration #15	2019-03-08	101.725 mi
Registration #16	2020-03-07	108.073 mi
Registration #17	2021-03-06	114.421 mi
Registration #18	2022-03-05	120.769 mi
Registration #19	2023-03-04	127.117 mi
Registration #20	2024-03-03	133.465 mi
Registration #21	2025-03-02	139.813 mi
Registration #22	2026-03-01	146.161 mi
Registration #23	2027-02-28	152.509 mi
Registration #24	2028-02-27	158.857 mi
Registration #25	2029-02-26	165.205 mi



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FX4C1972979