



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Black
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 2

Date	2022-08-17
Pictures	3
Listing price	View report


AutoTrader awards



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #18	2024-02-01 09:50
MOT test number	241454538893
Result	✓ Passed
Next expiry date	2025-02-14

MOT #17	2023-02-08 13:29
MOT test number	594675226444
Result	✓ Passed
Advice	Central Items removed from driver's view prior to test
Minor	Central Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #16	2023-02-01 12:39
MOT test number	974871054902
Result	✗ Failed
Advice	Central Items removed from driver's view prior to test
Minor	Central Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Front Lower Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Lower Coil spring fractured or broken broken section removed as close to tyre (5.3.1 (b) (i))

**MOT #15** 2022-01-29 11:41**MOT test number** 890533645414**Result** ✓ Passed**MOT #14** 2022-01-29 08:59**MOT test number** 216694099802**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #13** 2021-02-15 11:45**MOT test number** 778649194074**Result** ✓ Passed**MOT #12** 2021-02-12 11:21**MOT test number** 418025775892**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2020-11-23 16:10**MOT test number** 267223138136**Result** ✓ Passed**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10** 2019-12-09 15:39**MOT test number** 566157817752**Result** ✓ Passed**MOT #9** 2018-11-19 16:09**MOT test number** 491031746942**Result** ✓ Passed**MOT #8** 2017-12-14 09:20**MOT test number** 103716895712**Result** ✓ Passed**Advice** Nearside Rear perished**Advice** Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #7** 2016-11-22 11:50**MOT test number** 779910356247**Result** ✓ Passed**MOT #6** 2015-12-16 11:00**MOT test number** 247587738627**Result** ✓ Passed**Advice** Offside front, offside rear and nearside rear tyres perished**MOT #5** 2015-12-14 09:01**MOT test number** 424589212465**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside front, offside rear and nearside rear tyres perished**Fail** Offside Front coil spring broken (2.4.C.1a)



MOT #4	2014-12-05 11:30
MOT test number	909799634374
Result	✓ Passed
MOT #3	2013-12-04 12:03
MOT test number	138758233361
Result	✓ Passed
MOT #2	2012-11-29 13:50
MOT test number	496634132431
Result	✓ Passed
MOT #1	2011-12-12 11:26
MOT test number	288066441344
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 LM58YVP
Plate since	2019-09-29
Current registration	 LM58YVP
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-29
Last registration	2024-02-01
Complete history	See info



Registration #1	2009-01-29	26 mi
Registration #2	2011-12-12	7.043 mi
Registration #3	2012-11-29	10.183 mi
Registration #4	2013-12-04	14.796 mi
Registration #5	2014-12-05	18.930 mi
Registration #6	2015-12-14	21.921 mi
Registration #7	2015-12-16	21.921 mi
Registration #8	2016-11-22	23.914 mi
Registration #9	2017-12-14	25.670 mi
Registration #10	2018-11-19	26.506 mi
Registration #11	2019-12-09	27.281 mi
Registration #12	2020-01-29	28.000 mi
Registration #13	2020-02-29	28.000 mi
Registration #14	2020-03-29	28.000 mi
Registration #15	2020-04-29	28.000 mi
Registration #16	2020-05-29	28.000 mi
Registration #17	2020-06-29	28.000 mi
Registration #18	2020-07-29	28.000 mi
Registration #19	2020-08-29	28.000 mi
Registration #20	2020-09-29	28.000 mi
Registration #21	2020-10-29	28.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1150820