





General information

| Make | MINI |
|---------------------|----------------|
| Model | ONE |
| Colour | Orange |
| Year of manufacture | - |
| Top speed | 121 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power 101 BHP Max. torque 180 Nm at 1.400 rpm Cylinders 3 Fuel type Petrol | |
|--|-------------|
| Max. torque 180 Nm at 1.400 rpm 101 - 120 B 101 - 120 B 121 - 140 B <th>LABEL UNKNO</th> | LABEL UNKNO |
| Cylinders 3 121 - 140 P Fuel type Petrol 141 - 165 F | |
| Fuel type Petrol F | |
| | |
| Consumption city 49.6 mpg 166 - 185 | |
| Consumption extra urban70.6 mpg186 - 225 | |
| Consumption combined 61.4 mpg | L |





Internet history

Entry 1

Date Pictures 2021-06-13

14

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT #3 | | 2020-11-10 10:51 |
|-----------|--|------------------|
| MOT test | number | 725467802306 |
| Result | | ✓ Passed |
| Next expi | ry date | 2021-11-16 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | 2019-05-17 09:18 |
|--|------------------|
| MOT test number | 891485006331 |
| Result | ✓ Passed |
| Advice Manufactures sill and body covers fitted restricting inspection | |

| MOT #1 | | 2019-05-17 09:18 |
|-------------------------|---|------------------|
| MOT test number | | 842172162616 |
| Result | | 🗙 Failed |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice Manufactures si | l and body covers fitted restricting inspection | |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FERRE |
| Category | L'ARNO |
| Туре | |
| Domogo 2 | AMPLE |
| Damage 2 | 6 - 0 - 0 |
| Date | |
| Category | AMP |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 5 |
| First mileage registration | 2016-03-17 |
| Last registration | 2020-11-10 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-03-17 | 11 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-05-17 | 38.354 mi |
| Registration #3 | 2019-05-17 | 38.354 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.227 mi |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1727 mm |
| Height | 1414 mm |
| Length | 3821 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1570 kg |
| Additional information | |
| Fuel tank capacity | 40 |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 9/9 |

| Number of axles | 2 |
|-----------------|----------|
| Engine number | F119H161 |