



RENAULT

 **BG6ICZM**

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 DCI S/R P/V
Colour	White
Year of manufacture	2011
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-19
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-25
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	13
Total items failed	11

MOT #16	2024-01-26 17:17
MOT test number	384470635671
Result	✓ Passed
Next expiry date	2025-01-25

MOT #15	2024-01-26 14:19
MOT test number	263946890168
Result	✗ Failed
<div><div>Fail</div> Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))</div> <div><div>Advice</div> Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))</div> <div><div>Fail</div> Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))</div> <div><div>Advice</div> Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))</div>	

MOT #14	2023-01-12 11:46
MOT test number	851461272275
Result	✓ Passed

**MOT #13** 2023-01-11 16:59**MOT test number** 818342611947**Result** ✗ Failed**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #12** 2021-12-11 14:16**MOT test number** 841110250264**Result** ✓ Passed**MOT #11** 2021-12-11 12:33**MOT test number** 250340894841**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Nearside Rear Body component damaged and likely to cause injury tail light broken (6.2.1 (a) (i))**MOT #10** 2021-01-13 09:56**MOT test number** 517407754329**Result** ✓ Passed**MOT #9** 2020-01-30 13:31**MOT test number** 232119806068**Result** ✓ Passed

**MOT #8** 2020-01-30 13:31**MOT test number** 453125206613**Result** ✗ Failed**Pass with rectification** Front Position lamp not working BOTH SIDES (4.2.1 (a) (ii))**MOT #7** 2019-02-01 17:00**MOT test number** 801912375695**Result** ✓ Passed**MOT #6** 2018-02-05 09:52**MOT test number** 969359491474**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Tyre worn close to the legal limit both inner and outer edge (4.1.E.1)**MOT #5** 2018-02-05 09:52**MOT test number** 943766083840**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit both inner and outer edge (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2017-02-01 10:17**MOT test number** 190404431257**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2016-02-04 11:33**MOT test number** 410572466801**Result** ✓ Passed**MOT #2** 2016-02-01 14:34**MOT test number** 817686071509**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**Fail** Nearside Obligatory mirror missing (8.1.1)**MOT #1** 2014-12-06 09:22**MOT test number** 405840344312**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
25 January 2025

<b>Tax status</b>	Valid until 1 January
-------------------	-----------------------

<b>Days left</b>	247
------------------	-----

<b>MOT expiry date</b>	25 January 2025
------------------------	-----------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-24
Last registration	2024-01-26
Complete history	<a href="#">See info</a>



Registration #1	2011-12-24	17 mi
Registration #2	2014-12-06	33.292 mi
Registration #3	2016-02-01	47.085 mi
Registration #4	2016-02-04	47.097 mi
Registration #5	2017-02-01	52.714 mi
Registration #6	2018-02-05	78.850 mi
Registration #7	2018-02-05	78.850 mi
Registration #8	2019-02-01	98.631 mi
Registration #9	2020-01-30	116.832 mi
Registration #10	2020-01-30	116.832 mi
Registration #11	2020-01-30	116.832 mi
Registration #12	2020-01-30	116.832 mi
Registration #13	2020-01-30	116.832 mi
Registration #14	2020-01-30	116.832 mi
Registration #15	2020-01-30	116.832 mi
Registration #16	2020-01-30	116.832 mi
Registration #17	2020-01-30	116.832 mi
Registration #18	2020-01-30	116.832 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1967 mm
Length	5182 mm
Kerb weight	1660 kg
Max. allowed weight	2960 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C185544