



AY59XAS

report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg






Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT #14</b>	2022-11-18 09:15
<b>MOT test number</b>	447129327845
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-19
<b>Advice</b>	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))
<b>Advice</b>	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #13</b>	2021-10-29 09:12
<b>MOT test number</b>	195313485971
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #12</b>	2020-11-20 11:00
<b>MOT test number</b>	751049429977
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2019-11-20 16:49
<b>MOT test number</b>	490989048364
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Coil spring corroded Both rear coil springs corroded (5.3.1 (b) (i))
<b>Advice</b>	Rear exhaust silencer deteriorated
<b>Advice</b>	Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))
<b>Advice</b>	Front Suspension arm pin or bush worn but not resulting in excessive movement Both front wishbone rear bushes (5.3.4 (a) (i))
<b>Advice</b>	Rear view mirror missing

**MOT #10**

2019-11-20 16:49

**MOT test number**

365009028137

**Result****✗ Failed****Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Coil spring corroded Both rear coil springs corroded (5.3.1 (b) (i))**Advice** Rear view mirror missing**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both front wishbone rear bushes (5.3.4 (a) (i))**Advice** Rear exhaust silencer deteriorated**MOT #9**

2018-11-15 12:29

**MOT test number**

838174255919

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust rear section deteriorated

**MOT #8** 2018-11-14 15:47**MOT test number** 601040219885**Result** ✗ Failed

- MAJOR** Nearside Front Brake disc contaminated (1.1.14 (b))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Exhaust rear section deteriorated
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #7** 2017-10-23 15:22**MOT test number** 146866164024**Result** ✓ Passed

- Advice** Rear box corroded
- Advice** Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)

**MOT #6** 2017-10-23 15:22**MOT test number** 487931241142**Result** ✗ Failed

- Advice** Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** Rear box corroded
- Pass with rectification** Nearside Rear Brake cable insecure (3.5.1d)



<b>MOT #5</b>	2016-11-12 14:58
<b>MOT test number</b>	616223632946
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2015-08-13 11:35
<b>MOT test number</b>	289065025263
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2014-08-12 09:41
<b>MOT test number</b>	189554724278
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2013-08-12 11:16
<b>MOT test number</b>	538554023254
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2012-08-21 09:26
<b>MOT test number</b>	885594532201
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	AY59XAS
Plate since	2019-09-29
Current registration	AY59XAS
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-01
Last registration	2022-11-18
Complete history	<a href="#">See info</a>



Registration #1	2009-09-01	18 mi
Registration #2	2012-08-21	19.849 mi
Registration #3	2013-08-12	22.349 mi
Registration #4	2014-08-12	25.028 mi
Registration #5	2015-08-13	26.870 mi
Registration #6	2016-11-12	32.768 mi
Registration #7	2017-10-23	40.138 mi
Registration #8	2017-10-23	40.138 mi
Registration #9	2019-05-20	55.377 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434